

VAX/VMS
Systems Dispatch
September 1985
AD-L034A-27

digital
software



VAX/VMS SYSTEMS DISPATCH

Published by
Corporate Administrative Services Group, Software Services
Digital Equipment Corporation
129 Parker Street (PKO2/E49)
Maynard, MA 01754

The **VAX/VMS Systems Dispatch** contains new and revised Software Product Descriptions, programming notes, software problems statements and responses. Much of the material is developed from Software Performance Report (SPR) answers significant to the general audience and is printed here to supplement the maintenance updates.

DECnet-VAX
DECtype/VMS
VAX ReGIS Graphics Library
RTEM-11
VAX Ada
VAX ADE
VAX BASIC
VAX BLISS
VAX C
VAX CDD
VAX COBOL

VAX CORAL-66
VAX DATATRIEVE
VAX DBMS
VAX DECalc
VAX DECOR
VAX DIBOL
VAX DSM
VAX FMS
VAX FORTRAN
VAX MUX200
VAX PASCAL
VAX PL/I

VAX SPM
VAX TDMS
VAX 2780/3780 Protocol
Emulator
VAX 3271 Protocol
Emulator
FORTRAN IV/VAX to RSX
(Cross Compiler)
VAX SORT/MERGE
VAX
PDP DATATRIEVE/
VAX

DISTRIBUTION

The **VAX/VMS Systems Dispatch** is directed to one software contact for each software product. No mailing will be made to addresses without a software contact name. **Address change requests should be sent to the nearest DIGITAL field office. Include the new address and mailing label from the most recently received publication.**

Software binary and sources are provided under licenses only. The standard Terms and Conditions, OEM Agreement, and/or Quantity Discount Agreement contain the licenses for all binaries other than DECsystem-10.

Barbara Scollan, Associate Editor

Copyright © Digital Equipment Corporation 1985. All Rights Reserved.

The material in this document is for information purposes only. Digital believes the information in this publication is accurate as of its publication date; such information is subject to change without notice. Digital is not responsible for any inadvertent errors. Comments on the contents of this publication should be directed to your local Digital Field Office.

TRADEMARKS of DIGITAL EQUIPMENT CORPORATION
Maynard, Massachusetts

DEC
DECUS
DECnet
DECsystem-10
DECSYSTEM-20
DECwriter

DIBOL
EDUssystem
IAS
MASSBUS
PDP
PDT
RSTS

RSX
RT
ULTRIX
UNIBUS
VAX
VMS
VT

TABLE OF CONTENTS

		<u>Page</u>
HELPFUL HINTS FOR WRITING SPRS		1
<u>Component/ Product</u>	<u>Seq. No.</u>	
NEWS BULLETIN		
IMPORTANT VAX/VMS VERSION 4.2 INFORMATION	1.1.1	17
KNOWN PROBLEMS AND RESPONSES		
<u>VAX/VMS (V4.n)</u>		
SYS		
LACK OF DISK QUOTA CAUSES ERRFMT TO FAIL	5.20.8	21
GETJPI ("","TERMINAL") TRUNCATES NAMES	5.20.9	22
STARTUP		
TERMINAL LOGICAL NAMES IN UVSTARTUP.COM	10.15.1	25
LOGINOUT		
INCORRECT VALIDATION OF MAXJOBS	11.15.1	27
DEFCLI PROHIBITS CLI TABLE CHANGE IN SPAWN	11.15.2	28
NETWORK JOBS NOT COUNTED AGAINST MAXJOBS	11.15.3	29
SYSBOOT		
TOPSYS SYSTEM ROOT IS INCORRECT	11.30.1	31
SYSINIT		
SYSUAF.DAT REDEFINED FOR BYPASS AT LOGIN	11.40.2	33
VMSINSTAL		
VMSINSTAL GET OPTION FAILS ON VERSION 4 UPDATE	12.15.2	35
PRINT SYMBIONT		
CANNOT BYPASS ALL FORMATTING IN PRINT SYMBIONT	15.30.3	37
PRINT SYMBIONT ALLOCATES OUTPUT DEVICE	15.30.4	39
MULTIPLE PAGE HEADERS GENERATED BY PLOT	15.30.5	40
LOSS OF PRINT JOB WHEN CARRIER IS DROPPED	15.30.6	42
FILE LEFT OPEN BY PRINT SYMBIONT	15.30.7	43
IMPLICIT SPOOLING RESTRICTS USER	15.30.8	44
PRINT SYMBIONT PERFORMS TAB EXPANSION	15.30.9	45
PRINT SYMBIONT PROCESS TERMINATION	15.30.10	46
PRINT SYMBIONT ENTERS COMPUTE LOOP	15.30.11	49
MISCELLANEOUS PROBLEMS IN PRINT SYMBIONT	15.30.12	50
SERIAL PRINTERS ON DMF DISCONNECT	15.30.13	51
DCL		
CAPTIVE ACCOUNT CAUSES LOGINOUT ACCESS VIOLATION	20.5.1	53
CANNOT CHANGE/EXAMINE LOGICAL NAME TABLE PROT	20.5.2	54
DECnet		
STREAM LF FILE TRANSFER HANGS TO NON-VMS PARTNERS	25.5.5	55
DECnet GIVES INCORRECT ERROR ON INVALID USER NAME	25.5.6	56
DDDRIVER		
TU58 TIMES OUT WHEN /DATA_CHECK=WRITE IS USED	31.10.1	57

TABLE OF CONTENTS (Cont.)

<u>Component/ Product</u>	<u>Seq. No.</u>	<u>Page</u>
EDIT/ACL		
EDIT/ACL DELETES ACE GRANTING ACCESS	35.5.1	59
PROBLEM IN REFRESH LOGIC CAUSES ACCESS VIOLATION	35.5.2	60
MISSING STATUS RETURN	35.5.3	61
CONVERT		
CONVERT INCORRECTLY RETURNS RTL ERROR	40.5.3	63
RMS		
FILE CORRUPTION WITH GLOBAL BUFFERS	40.45.6	65
SYS\$RMSRUNDN RETURNS INCORRECT STATUS	40.45.7	66
SEARCH LIST QUESTIONS	40.45.8	67
REMOTE COMMAND PROCEDURES FAIL	40.45.9	68
VERSION 4 COPY WILL NOT COPY VERSION 3 ISAM FILES	40.45.10	69
RMS FILE PARSE PROBLEM WITH LEVEL 8 DIRECTORIES	40.45.11	71
AUTHORIZE		
CLARIFICATION OF ADD/NETWORK	55.10.3	73
AUTHORIZE AND DISKQUOTA DO NOT RETURN STATUS	55.10.4	74
PROBLEM WITH SHOW/ID FOLLOWED BY MOD/ID	55.10.5	75
DEBUG		
SET MODULE COMMAND TAKES TOO LONG	55.50.1	77
COMMA LISTS ON DEPOSIT NOT ALLOWED	55.50.2	78
LINKER		
VERSION 4.0 IMAGES LARGER THAN VERSION 3.0 IMAGES	56.20.3	79
MAIL		
MAIL CANNOT RUN ON A GIGI TERMINAL	56.30.1	81
MONITOR		
FOREIGN TERMINAL SUPPORT DOES NOT WORK	56.40.1	83
MONITOR'S VIRTUAL MEMORY USAGE GROWS CONTINUOUSLY	56.40.2	84
PURGE		
PURGE CAN INCORRECTLY DELETE FILES	56.52.1	85
SET		
VOLUME RETENTION DATES OVERRIDE SET FILE DATES	56.80.2	87
SET PASSWORD ALWAYS RETURNS SUCCESS STATUS	56.80.3	88
SHOW CLUSTER		
CNX_STATE DOCUMENTATION ERROR	56.85.1	89
SHUTDOWN		
SHUTDOWN\$INFORM_NODES USAGE DESCRIBED	56.90.1	91
TIME-OF-YEAR CLOCK CAUSES SHUTDOWN ERROR	56.90.2	93
SPAWN		
CANNOT SPECIFY SPOOLED DEVICE WITH SPAWN	57.10.1	95
LIB\$SPAWN FAILS WITH MBFULL	57.10.2	96
DOCUMENTATION		
SYS\$GETJPI DOCUMENTATION ERRORS	65.5.4	97
SYS\$GETJPI DOCUMENTATION ERROR	65.5.5	98
CHAN ARGUMENT INCORRECT FOR \$GETDVI	65.5.6	99

TABLE OF CONTENTS (Cont.)

<u>Component/ Product</u>	<u>Seq. No.</u>	<u>Page</u>
REPUBLISHED ARTICLES		
CONVERT		
CONVERT/RECLAIM MAY ACCESS VIOLATE	40.5.1	105
CONVERT CAN INCORRECTLY REPORT DUP AND SEQ ERRORS	40.5.2	106
RMS		
READ FROM SYS\$OUTPUT FAILS	40.45.1	107
COPY/OVERLAY FAILS IF DESTINATION WRITE-PROTECTED	40.45.2	108
CONFUSION ON \$CREATE USING SEARCH LISTS	40.45.3	109
RENAME RETURNS INCORRECT ERROR MESSAGE	40.45.4	110
ACCESS CONTROL STRING PARSED INCORRECTLY	40.45.5	111
VERSION 4 ENHANCEMENTS		
ENHANCEMENTS IN VERSION 4.0 DCL	62.5.1	117
ARTICLES OF GENERAL INTEREST		
DUDRIVER		
SYSTEM DISK MOUNT VERIFICATION TIMEOUT	95.5.5	123
DIRECTORY AND SEARCH LIST CONFUSION	95.5.6	125
DATE/TIME CLOCK		
"DOES ANYBODY REALLY KNOW WHAT TIME IT IS? DOES ANYBODY REALLY CARE?"	95.5.7	127
CUMULATIVE INDEX		131
COMPONENTS LIST		135
SOFTWARE PROBLEMS OR ENHANCEMENTS		145
DIGITAL SOFTWARE LICENSING		147
DIGITAL EQUIPMENT COMPUTER USERS SOCIETY (DECUS)		149



.

.



.

.



**HELPFUL HINTS
FOR WRITING
SPRs**



•

•



•

•



HINTS FOR WRITING SPRS

1.0 Introduction

Software Performance Reports (SPRs) exist to benefit customers as well as DIGITAL. They provide information to customers and feedback to DIGITAL about software problems.

The following descriptions provide guidelines for submitting information to DIGITAL so that SPR problems can be solved. Some information is common to all SPRs; other information is requested for only certain types of problems.

2.0 SPR Priority Levels

The following explanations of SPR priorities should be used as a guideline for determining the priority of an SPR. Please note that the priority determination should be based on the system or facility behavior that has actually been experienced at the site and should not be based on the perception of the impact of a potential problem.

Priority	Explanation
1.	MOST PRODUCTION WORK CANNOT BE RUN e.g., important production software is unusable, the system will not boot, necessary peripherals cannot be used as intended, no workaround exists.
2.	SOME PRODUCTION WORK CANNOT BE RUN e.g., certain functions or jobs are not usable, level of performance is not as expected or some documented feature does not work as expected but there is a workaround.
3.	ALL PRODUCTION WORK CAN BE RUN WITH SOME IMPACT ON USER e.g., significant manual intervention is required, performance has degraded but work can still be done.
4.	ALL PRODUCTION WORK CAN BE RUN WITH NO SIGNIFICANT IMPACT ON USER e.g., problem can be patched easily, simple bypass procedure exists.
5.	NO SYSTEM MODIFICATIONS NEEDED TO RETURN TO NORMAL PRODUCTION e.g., suggestion, consultation, documentation error or inquiry.

3.0 General Guidelines

This section covers the information that should be provided with all SPRs. Depending upon the problem, this information will vary in quantity and content. Remember that the more pertinent information that is included, the easier it is for DIGITAL to resolve the problem.

3.1 Scenario

A complete scenario should be supplied, usually in the form of a batch log console listing or SET HOST/LOG output file that shows exactly how the problem is produced. Supplying only the output produced by the problem is not enough. The entire scenario of what was done by the user is needed. The problem may be caused by an interaction between various system events, software packages, devices, SYSGEN parameters, DCL symbols or logical names. Some or all of the displays generated by the following commands may be required for different problems:

```
$ SHOW LOGICAL/ALL/FULL
$ SHOW SYMBOL/ALL/GLOBAL

$ RUN SYS$SYSTEM:SYSGEN
SYSGEN> USE ACTIVE
SYSGEN> SHOW/ALL
SYSGEN> SHOW/SPECIAL
SYSGEN> EXIT
```

3.2 Limit Problem Scope

As much as possible, eliminate all extraneous elements from the scenario. For example, if the execution of a very large program causes a problem, shorten the program to include only the code that causes the problem or write a small program that demonstrates the problem. This action has two benefits: first, logic errors may be discovered; second, the maintainer looking into the problem does not have to comprehend unnecessary material.

3.3 Machine-readable Files

If possible, supply any software needed to reproduce the problem. This may include source programs, image files, sample data, command procedures, logical names etc. If source programs are submitted, also include any libraries or require files referenced. These files must be provided in machine-readable format. Console medium or ANSI magtape are the best media to include with the SPR.

If the problem involves a system crash, include the system dump.

The data should be written to an ODS-2 format disk or an ANSI magtape. For example, the following commands will copy the system dump file to an ANSI magtape:

```
$ INIT MTA0: DUMPS
$ MOUNT/FOREIGN MTA0:
$ BACKUP/IGNORE=NOBACKUP SYS$SYSTEM:SYSDUMP.DMP -
  $ MTA0:DUMPS/SAVE
$ DISMOUNT MTA0:
```

NOTE

Since the system dump file is frequently marked NOBACKUP (telling the BACKUP utility to copy the file attributes but not its contents), the dump file be must copied with:

BACKUP/IGNORE=NOBACKUP

This will insure that the file contents are copied, as well as the file attributes. The commands used to write the media should also be provided with the SPR.

On a MicroVAX, where there is no console block storage device, use one of the floppy diskette drives to create machine-readable medium to be included with the SPR. The following commands can be used to copy files:

```
$ INIT $FLOPPY1: SPRDATA
$ MOUNT $FLOPPY1: SPRDATA
$ CREATE/DIRECTORY $FLOPPY1:[DUMP]
$ BACKUP MYDATA.DAT,MYIMAGE.EXE $FLOPPY1:[DUMP]SPRDATA/SAVE
$ DISMOUNT $FLOPPY1:
```

On a full VAX, where there is a console block storage device, the following commands can be used to copy machine-readable data:

```
$ RUN SYS$SYSTEM:SYSGEN
SYSGEN> CONNECT CONSOLE
SYSGEN> EXIT
```

(At this time, remove the console medium and place a scratch volume in the console block storage device.)

```
$ INIT CSAL: SPRDATA
$ MOUNT CSAL: SPRDATA
$ CREATE/DIRECTORY CSAL:[DUMP]
$ BACKUP MYDATA.DAT,MYIMAGE.EXE CSAL:[DUMP]SPRDATA/SAVE
$ DISMOUNT CSAL:
```

It is important to use BACKUP to write the media submitted with an SPR. Transferring files in a save set produced by BACKUP is much more reliable than copying files to the media.

When machine-readable data is not provided in BACKUP save-set format, include the exact commands that were used to write the data and the commands used for reading it. Other formats are discouraged, since they may cause problems.

All machine-readable media submitted with SPRs will be returned to the customer.

3.4 System Environment

Every computer site runs a different type of workload. Some problems only appear under certain conditions. For example, some sites give different classes of users different base priorities. These sites may encounter problems that other sites do not. This information can be extremely important in resolving the problem, especially for system hangs or system crashes.

Describe any special software packages that are being used. Also, mention any foreign hardware devices or user-written drivers.

Software version numbers should be included. For example, if there is a problem with accessing local symbols during a DEBUG session, the version numbers of DEBUG and all relevant compilers/assemblers should be specified.

If any patches other than those from maintenance updates are being used, they should be mentioned in the SPR.

3.5 User Analysis (Optional)

Optionally, an analysis of the problem may be included. Any useful miscellaneous information should be included, such as, "Without xyz happening, the problem could not be reproduced" or "On version Vx.y, this problem does not occur."

4.0 Problem-specific Information to Include

Resolution of different classes of problems generally requires different kinds of additional information.

NOTE

For those items that are identified with a single asterisk (*), the raw data file (SYS\$ERRLOG:ERRLOG.SYS), not the formatted output from the ANALYZE/ERROR utility, should be included. Formatted output frequently does not include all the information needed to resolve the problem.

For those items that are identified with a double asterisk (**), the raw data file (SYS\$SYSTEM:SYSDUMP.DMP), not the formatted output from the SDA utility, should be included. Formatted output usually does not include all the information needed to resolve the problem.

Problem	Information to Include
System Bugcheck/Crash	<p>A machine-readable copy of the system dump file must be included.** (Output from the SDA utility should <u>not</u> be sent since it usually does not include enough information to resolve the problem).</p> <p>A copy of the error log at the time of the error should also be included because many system problems are triggered by hardware errors.*</p>
Machine-check:	<p>On a machine check, include a machine-readable copy of the error log, not output from the error log generator.*</p> <p>A machine-readable copy of the system dump file should also be included. **</p>
System Hang:	<p>When a system appears "hung" (no response on any terminals), the system should be manually crashed and the system dump file included with the SPR.</p> <p>When the system is shut down in this way, <u>the console listing is very important</u> and should be included with the SPR.</p>

On VAX-11/730, VAX-11/780, VAX-11/782, VAX-11/785, and VAX 8600 primary console terminals, enter: (do nothing on the attached processor's console)

^P
HALT
@CRASH

On VAX-11/750 console terminal,
enter:

```
^P
E P
E/I 0
E
E
E
E
D/G F FFFFFFFF
D P 1F0000
C
```

On MicroVAX I:

Push the HALT button on the front panel of the CPU box twice, so that the button is latched out (the red light in the center of the button is out).

Then, on the console terminal, enter:

```
E P
E/I 0
E +
E +
E +
E +
D/G F FFFFFFFF
D P 1F0000
C (Then wait a minute or so)
```

Note: If a CRT is being used, copy the displayed values from the examine commands to paper and submit them with the SPR.

The preceding command sequences cause the VAX or MicroVAX system to bugcheck in a manner that is recognized by VMS developers as a forced crash.

Also include a description of the currently running workload.

VAXclusters:

If all machines in a VAXcluster are "hung" for a reason other than an explainable lack of quorum, a coordinated set of dumps plus console listings from all machines may be required for diagnosis. A coordinated set of dumps is a dump from every machine in the cluster taken in a way that ensures that the lock and other data structures are consistent between all dumps. To take a coordinated dump, first halt every VAX in the cluster. The last machine must be halted no more than 99 seconds after the first machine is halted. After all machines have been halted, crash each machine as directed under SYSTEM HANG, and provide all of the dumps and all of the console logs with your SPR.

Executive:

If it appears that there is a problem with the executive code, include the active values of the system parameters. These can be obtained by invoking SYSGEN and entering both the SHOW/ALL and SHOW/SPECIAL commands.

A machine-readable copy of the source program showing the problem plus libraries, require files, and build files should also be included, if possible.

Also include a copy of the machine-readable error log at the time of the problem. *

Devices:

For any suspected device or device driver error, include a copy of the error log at the time of the problem. *

Corrupted RMS Files:

When an RMS file becomes corrupted by software, an SPR should always be submitted. Items to include with the SPR are:

- 1) A copy of the corrupted file.
- 2) Any programs (preferably with sources) and data that are necessary to reproduce the corruption. Note the distinction between programs that merely demonstrate that the file is corrupt, as opposed to a program that causes the corruption to occur. Please try to trim down the program to isolate the specific operations that led to the corruption.
- 3) A description of how the file is being processed when the corruption occurs. For example, how many users are accessing the file, what kind of operations are being performed on the file (\$UPDATES, \$PUTS, \$DELETES, etc.).

Sometimes accessing a corrupted file can cause nonfatal bugchecks. If it appears that a process is continually disappearing from the system, check the error log for nonfatal bugchecks. If this is the case, include a crash dump with the SPR. To obtain a crash dump (assuming the system manager has given permission), perform the procedure below. Since this procedure will crash the system, it is suggested that it be performed during off-peak hours. Be sure to give adequate warning if there are any users on the system.

```
$ RUN SYS$SYSTEM:SYSGEN
SYSGEN> USE ACTIVE
SYSGEN> SET BUGCHECKFATAL 1
SYSGEN> WRITE ACTIVE
SYSGEN> EXIT
$ RUN PROGRAM_THAT_BUGCHECKS
```

Intermittent:

For a problem that is intermittent or that is not reproducible, include a copy of the machine-readable error log at the time of the problem. *

Command Language
Interpreters:

When submitting an SPR on a command language interpreter, it is important to show all symbols and logical names defined on the system by using the following commands:

```
SHOW SYMBOL/ALL/GLOBAL
SHOW SYMBOL/ALL/LOCAL
SHOW LOGICAL/ALL/FULL
```

Also, indicate whether private or modified command tables are being used.

Job Controller:

If the job controller process encounters a fatal error condition, it aborts execution and restarts itself (as a new process). Upon restart, the system job queue file is not reopened automatically; a START/QUEUE/MANAGER command and appropriate START/QUEUE commands must be manually issued to restart batch and print processing for that node.

For this type of controller problem, include a copy of the console log error message and a machine-readable copy of the job controller process dump written by the system to SYS\$SYSTEM:JOBCTL.DMP. In addition, if the START/QUEUE/MANAGER command fails because of a corrupted system job queue file, also include a machine-readable copy of the queue file. The default queue file name is SYS\$SYSTEM:JBCSYSQUE.DAT.

Print Symbiont:

Print symbiont process dump:

If the print symbiont exits, a message from the job controller is printed on the console, together with an error message from the print symbiont. Also, a symbiont process dump is written

to SYS\$SYSTEM:PRTSMB.DMP. Include a copy of these console log messages and a machine-readable copy of the symbiont process dump. Also include copies of the displays:

- SHOW QUEUE/FULL/ALL
- SHOW PRINTER (for all
printer execution queues)
- SHOW QUEUE/FORM/FULL
- SHOW TERMINAL (all terminal
execution queues)

If a file was involved, include a DIRECTORY/FULL of the file and, if possible, a machine-readable copy of the file. If at all possible, attempt to explain the conditions which directly preceded the symbiont exit, such as commands used or attempted, and/or a detailed description of the symbiont behavior prior to exiting.

Unexpected format or output generated with print symbiont:

If the print symbiont problem exists in the formatting or output of data, include a machine-readable copy of the file and the library modules in use when printing.

Include a DIRECTORY/FULL display of the file and a copy of the displays using the following commands:

- SHOW QUEUE/FULL/ALL
- SHOW QUEUE/FORM/FULL
- SHOW PRINTER and/or SHOW TERMINAL
(whichever is applicable)

Along with a description of the explicit PRINT command, include qualifiers and a copy of the FILE TRAILER page. Please provide all information required to reproduce the behavior consistently.

User-written and user-modified symbiont problems:

Describe the problem as completely as possible, including the intent of the user symbiont. Supply all details surrounding the problem and include a well-commented listing of the user-supplied symbiont or

routine. If the problem is associated with the specification of the queue, form, characteristics, parameters, or other input to the DCL command line, include a log file or a description of the PRINT command which demonstrates the problem.

LIBRARIAN:

If there is a problem with the LIBRARIAN, include the following material:

1. A machine-readable copy of the library itself
2. Machine-readable copies of all input files to the library
3. Information (DIRECTORY/FULL) on the library file
4. Information (LIBRARY/LIST/FULL) on the library contents

If the problem can be duplicated at will, include the scenario and any command files used.

LINKER:

If there is a problem with the LINKER, include machine-readable copies of the object files, shareable images, and libraries used in the link, along with a full map (LINK/MAP/FULL).

Debugger:

Include sources, objects, and images for the program being debugged. If the program is large, it would be very helpful to reduce the size of the program to demonstrate the same problem. Also include a log of the debugging session and include the DEBUG.LOG file that the debugger produces.

DECnet:

For a DECnet problem, supply configurations of the systems involved in the problem. This information should include the version numbers of the operating systems and DECnet, the hardware on both systems, and the patch level of the DECnet software on the non-VMS system, if applicable. Depending on the nature of the problem, it might also be applicable to supply hard-copy display of executor, line or circuit parameters and/or counters.

Terminals:

If there is a problem with the terminal driver, provide the following information:

1. A list of terminal characteristics (SHOW TERMINAL)
2. The type of terminal
3. The type of modem (if any)
4. Any special front-end equipment
5. Any unusual terminal configuration

If the problem involves remote file access, it is often useful for the maintainer to know if the same or similar operation can be performed from a different account, or with the source and destination nodes reversed.

Compiler/Assembler:

If there is a problem with the assembler or a compiler, include the source program that caused the problem. (It is very important to include all require files and libraries that are referenced by the source program).

It is especially important to limit the scope of the problem when submitting SPRs on compilers.

Include the version number of the compiler and the version number of the operating system.

NEWS BULLETIN

Important VAX/VMS Version 4.2 Information

The following information helps clarify the installation procedures contained in the VAX/VMS Release Notes, Version 4.2, and stresses the importance of installing or upgrading correctly.

There are two methods by which VAX/VMS Version 4.2 can be brought up.

METHOD 1

Perform a complete installation onto a blank disk. This method has no restrictions. If a system is currently running VAX/VMS Version 3.n, there might be problems with the installation of layered products.

METHOD 2

Perform an upgrade to an existing system. This method has two restrictions:

1. The system to be upgraded must be VAX/VMS Version 4.0 or later. The upgrade will not work on any earlier version of VAX/VMS.
2. The upgrade kit and files must be on a device that is distinct from the system device. Most upgrades are done directly from the distribution media. Do not copy the files from the distribution media to the system disk. The upgrade does not work under these circumstances.

In either case, the mandatory update must be applied after the upgrade or installation has finished. In the case of MicroVMS, the update must be applied after the base kit, and again after any options or layered products have been installed. The installation of MicroVMS options and layered products will not succeed unless the mandatory update has been applied.

KNOWN PROBLEMS AND RESPONSES



•

•



•

•



OPERATING SYSTEM: VAX/VMS V4.0
PRODUCT: VAX/VMS
COMPONENT: SYS

Seq. 5.20.8

Lack of disk quota causes ERRFMT to fail

PROBLEM STATEMENT

After upgrading from VAX/VMS Version 3.7 to VAX/VMS Version 4.0, the ERRFMT process fails to run. This failure is a result of the ERRFMT process having neither disk quota on the system disk nor the EXQUOTA privilege. Prior to VAX/VMS Version 4.0, the ERRFMT process was given the EXQUOTA privilege.

RESPONSE

The ERRFMT process is no longer given the EXQUOTA privilege. This avoids the potential problem of a malfunctioning device consuming excessive space on the system disk with entries. This modification creates an unintentional side effect of disabling error logging on systems which have disk quotas enabled on the system device, but no entries for the ERRFMT's UIC.

In a future update to VAX/VMS, we intend to document this behavior more completely and, if necessary, allocate a reasonable quantity of disk quota for the ERRFMT process.

OPERATING SYSTEM: VAX/VMS V4.0
PRODUCT: VAX/VMS
COMPONENT: SYS

Seq. 5.20.9

GETJPI ("","TERMINAL") truncates names

PROBLEM STATEMENT

When using VAX/VMS Version 4.0 with virtual terminals enabled, after many logins, the virtual terminal names reach a length of over 7 characters ("VTAl000:").

These terminal names, when returned by \$GETJPI, are truncated to 7 characters ("VTAl000:" is truncated to "VTAl000"), producing an error for the following case:

```
$ TERM = F$GETJPI("","TERMINAL")
$ DEFINE/USER SYS$INPUT 'TERM'
$ EDIT FOO.COM
```

RESPONSE

It is true that \$GETJPI returns an invalid terminal name if the name length reaches 7 characters (the colon is dropped from the returned string even though it returns an 8 byte string). We expect that this problem will be fixed in a future major release of VAX/VMS.

Note, however, that excluding the missing colon, the actual device name is correct. Therefore, the following workaround can be used, regardless of the length of the terminal name:

```
$ TERM = F$GETJPI("","TERMINAL")
$ TERM = TERM - ":" + ":"
$ DEFINE/USER SYS$INPUT 'TERM'
$ EDIT FOO.TXT
```


The second command insures that a colon is appended to the end of the terminal name whether or not one already exists.

This problem exists for any call to \$GETJPI with the item code JPI\$TERMINAL. Programs which call \$GETJPI should include code to handle the case of a missing colon.

OPERATING SYSTEM: VAX/VMS V4.0
PRODUCT: VAX/VMS
COMPONENT: STARTUP

Seq. 10.15.1

Terminal logical names in UVSTARTUP.COM

PROBLEM
STATEMENT

If a MicroVAX contains more than one terminal controller, the MicroVMS logical names \$TERMINAL1, \$TERMINAL2, etc., might be defined incorrectly.

RESPONSE

In a future update, we expect to correct UVSTARTUP.COM so it does not try to define these logical names twice if there is more than one terminal controller.

OPERATING SYSTEM: VAX/VMS V4.0
PRODUCT: VAX/VMS
COMPONENT: LOGINOUT

Seq. 11.15.1

Incorrect validation of MAXJOBS

PROBLEM
STATEMENT

Batch process login is incorrectly validated against the user quota MAXJOBS. If MAXJOBS is set to N, N+1 jobs are admitted.

RESPONSE

This problem is corrected in VAX/VMS Version 4.2.

OPERATING SYSTEM: VAX/VMS V4.0
PRODUCT: VAX/VMS
COMPONENT: LOGINOUT

Seq. 11.15.2

DEFCLI prohibits CLI table change in SPAWN

PROBLEM
STATEMENT

The DEFCLI flag prohibits the user from changing command tables in a SPAWN command. No error message is given; rather, the spawned process executes with the standard command tables, giving potentially unexpected results.

RESPONSE

Since the CLI tables are viewed as an extension of the CLI, it is necessary to restrict changing them to enforce the intent of the DEFCLI flag correctly.

In a future update of VAX/VMS, we expect to give a suitable error message when SPAWN/CLI is specified.

OPERATING SYSTEM: VAX/VMS V4.1
PRODUCT: VAX/VMS
COMPONENT: LOGINOUT

Seq. 11.15.3

Network jobs not counted against MAXJOBS

PROBLEM STATEMENT

The authorization record fields MAXJOBS and MAXACCTJOBS do not apply to network processes. As a result, a user performing remote file access operations can consume system resources beyond normal limits.

RESPONSE

The exemption of network jobs from the job quotas results from the behavior of network file access. It is possible for the accessor to close a file and request access to a new file before the NETSERVER process (running FAL) is ready to accept the next transaction. Under this circumstance, DECnet starts a new NETSERVER process. As a result, it is possible to create multiple NETSERVER processes on the remote node, all serving the same series of requests. Denying the creation of any of these processes causes the file access operation to fail at the initiating node. The most common occurrence of this situation is when the user performs a wildcard remote file access operation.

In VAX/VMS Version 4.2, network processes are counted against the MAXJOBS quota with an exemption of up to four network processes per user. This represents a compromise between preventing users from flooding the system and allowing wildcard network file access to function correctly.

At some later date, we expect to provide a more comprehensive solution to this problem.

OPERATING SYSTEM: VAX/VMS V4.0
PRODUCT: VAX/VMS
COMPONENT: SYSBOOT

Seq. 11.30.1

TOPSYS system root is incorrect

PROBLEM
STATEMENT

VMS does not handle the VMB input, TOPSYS, correctly. Somewhere between the time when VMB finds SYSBOOT and when the STARTUP.COM command procedure is executed, the value of TOPSYS is altered from [SYS5.] to [SYS0.].

RESPONSE

The behavior described above can be caused by booting VMS using a pre-Version 4 copy of VMB. While it does not seem likely that an old version of VMB would exist on the Version 4 system disk, it is possible that an old version exists on the console media. Older versions of VMB do not pass the TOPSYS input through to the running system, and a default of [SYS0.] is used.

Because VMB is decoupled from the rest of the VMS system, it is our goal that VMB be forward and backward compatible with the rest of VMS. Care is taken to insure that new versions of VMB will boot the previous version of VMS and that old versions of VMB will boot the next version of the VMS operating system. However, forward compatibility is restricted by the fact that old versions of VMB will never be able to boot using hardware or software capabilities that are introduced in the newer versions of VMS.

A workaround is to update the VMB on the console media with the VMB.EXE from the VAX/VMS Version 4.0 system disk.

OPERATING SYSTEM: VAX/VMS V4.0
PRODUCT: VAX/VMS
COMPONENT: SYSINIT

Seq. 11.40.2

SYSUAF.DAT redefined for bypass at login

PROBLEM
STATEMENT

In the MicroVMS User's Manual, page 1-16, under Section 1.2.5.1, "Alternate User Authorization File" there are instructions for breaking into a locked system. This method does not work. If the instructions are followed and "ANYTHING" is typed for the user name and password, an error occurs indicating user authorization failure. There is no alternate UAF file present on the system. If SET UAFALTERNATE 1 is set at the SYSBOOT prompt, the correct system password (that is, the one in the default UAF file) still allows access to the system.

RESPONSE

The procedure does not work as documented because of an incorrectly defined logical name in SYS\$SYSTEM:SYSINIT.EXE. The MicroVMS User's Manual, Chapter 1, covers the correct procedure for using an alternate user authorization file to break into a locked system.

The error in SYSINIT.EXE is corrected in VAX/VMS Version 4.2.

OPERATING SYSTEM: VAX/VMS V4.0
PRODUCT: VAX/VMS
COMPONENT: VMSINSTAL

Seq. 12.15.2

VMSINSTAL GET option fails on Version 4 update

PROBLEM STATEMENT

The GET option on VMSINSTAL does not work for the Version 4.0 mandatory update because the BACKUP save sets do not follow expected naming conventions.

RESPONSE

This problem will be avoided by using proper save set naming conventions for future updates of VAX/VMS.

A workaround is to use COPY to preserve all necessary BACKUP save sets.

OPERATING SYSTEM: VAX/VMS V4.0
PRODUCT: VAX/VMS
COMPONENT: PRINT SYMBIONT

Seq. 15.30.3

Cannot bypass all formatting in print symbiont

PROBLEM STATEMENT

The VAX/VMS Version 4.0 standard print symbiont does not provide a mechanism to suppress all formatting or bypass the buffering of output. The PRINT/PASSALL command does not allow data to be passed to the driver without the formatting of output.

RESPONSE

The PRINT command qualifier /PASSALL, supported in VAX/VMS Version 4.0, is intended to allow the user to bypass interpretation of data by the main format routine. However, the current implementation of this qualifier in the standard symbiont does not perform as intended.

In VAX/VMS Version 4.2, the DCL command PRINT/PASSALL bypasses all formatting.

In the meantime, formatting by the symbiont may be avoided by using form definitions and the /PASSALL and /NOFEED qualifiers of the DCL PRINT command. The insertion of carriage return and line feed at the right margin may be avoided by defining a form as /NOWRAP and /NOTRUNCATE.

For example:

```
$ DEFINE/FORM /NOWRAP /NOTRUNCATE /STOCK=DEFAULT
  _Form name: NOFORMAT
  _Form number: 2
```

This form, together with the /PASSALL qualifier, must be specified on the PRINT command. For example, to print the file FOOBAR.TXT, use the following command:

```
$ PRINT/FORM=NOFORMAT /PASSALL FOOBAR.TXT
```

The insertion of form feeds by the symbiont at the bottom margin can be avoided by using the DCL command:

```
$ SET QUEUE/DEFAULT=NOFEED
```

Not all formatting will be bypassed with the above suggestions. However, defining a form /NOWRAP and /NOTRUNCATE and setting the queue /DEFAULT=NOFEED might help.

OPERATING SYSTEM: VAX/VMS V4.0
PRODUCT: VAX/VMS
COMPONENT: PRINT SYMBIONT

Seq. 15.30.4

Print symbiont allocates output device

PROBLEM
STATEMENT

It is not possible to start an output queue on a device that is allocated to another user. Issuing the DCL command START/QUEUE when another process has the device opened for output results in an error.

RESPONSE

This behavior is intentional. When the output queue is started, the print symbiont allocates and assigns a channel to the output device. The allocation of the device prevents users from accessing the device. The output device is allocated until the output queue is stopped.

OPERATING SYSTEM: VAX/VMS V4.1
PRODUCT: VAX/VMS
COMPONENT: PRINT SYMBIONT

Seq. 15.30.5

Multiple page headers generated by plot

PROBLEM STATEMENT

PRINT/HEADER/NOFEED is used to produce a plot with a page header on an LXY22 plotter. The print symbiont prints a header line, a form feed, and then continues the true plot. During the processing of the true plot, more page headers are output by the symbiont. The page header appears to be output to the device whenever the total number of lines on the page is exceeded. It appears the symbiont is counting the number of records written and issuing page headers when the line count exceeds that of the form definition.

RESPONSE

The VAX/VMS Version 4.0 print symbiont creates a page header for output to the device if page headers are active and the current page is considered a new page. A page is considered new if the number of lines left on the page is zero. The number of lines left on the page is equal to the form length minus the current line count. If the bottom margin is nonzero, the form length is further reduced by the size of the bottom margin. The current line count is changed whenever a vertical format effector is encountered by the standard VAX/VMS Version 4.0 print symbiont.

The prefix carriage control character of every record in a particular FORTRAN file is a hexadecimal 20 or space character. As documented in the VAX/VMS I/O User's Reference Manual, Part I, pp. 5-6 through 5-8 and the VAX/VMS Utility Routines Reference Manual, pp. 5-21 through 5-22, a space character in the prefix area of a FORTRAN carriage control record indicates that a line feed should be inserted before the FORTRAN record.

The print symbiont performs the interpretation of FORTRAN carriage control prefix character, inserts the required format effector, and, depending upon the interpretation, changes the current column, line or page position. Line feed, in this case, increments the current internal line count of the print symbiont. A new page is generated by the symbiont when the current line count of the symbiont exceeds the length of the form. A page header is created if page headers are active and a new page is generated by the symbiont.

A single page header at the top of the page can be achieved by creating a form with a length that exceeds the total number of line feeds specified by the records.

OPERATING SYSTEM: VAX/VMS V4.1
PRODUCT: VAX/VMS
COMPONENT: PRINT SYMBIONT

Seq. 15.30.6

Loss of print job when carrier is dropped

PROBLEM
STATEMENT

When carrier is dropped on a remote printer, the current print job is not requeued as specified in the VAX/VMS Release Notes, Version 4.0, but is lost and must be resubmitted.

RESPONSE

The VAX/VMS Release Notes, Version 4.0, incorrectly states that the current job is requeued for printing upon loss of carrier. The default behavior for output queues upon detection of error is loss of the current job. This default behavior can be overridden by setting the queue attribute for retention of jobs upon detection of error.

The following DCL command sets this queue attribute for the output queue named FOO:

```
$ SET QUEUE/RETAIN=ERROR FOO
```

If a job is retained in an output queue as a result of the queue attribute /RETAIN=ERROR, operator intervention is required to release that job for printing. The following DCL command releases a retained entry for printing in the output queue FOO:

```
$ SET QUEUE/ENTRY=entry-number /RELEASE FOO
```

OPERATING SYSTEM: VAX/VMS V4.1
PRODUCT: VAX/VMS
COMPONENT: PRINT SYMBIONT

Seq. 15.30.7

File left open by print symbiont

PROBLEM STATEMENT

When attempting to dismount a user disk, it is discovered that the print symbiont has left a file open.

The following two conditions exist:

1. The symbiont is idle with no current jobs.
2. The queues are not spooled to this disk.

RESPONSE

This problem is fixed in VAX/VMS Version 4.2.

As a temporary workaround, stop all queues served by that symbiont with the DCL command:

\$ STOP/NEXT queue

This causes the symbiont process to close all files and exit.

OPERATING SYSTEM: VAX/VMS V4.0
PRODUCT: VAX/VMS
COMPONENT: PRINT SYMBIONT

Seq. 15.30.8

Implicit spooling restricts user

PROBLEM STATEMENT

Software that creates plots for a non-DIGITAL plotter uses implicit spooling for the submission of plot files to the output queue. When the plot files are written by the print symbiont, form feeds are inserted. A workaround is to create an intermediate file and to submit this file for plotting using the DCL command PRINT/NOFEED. Setting the output queue to /DEFAULT=NOFEED does not work because other users rely on the form feed capability of the symbiont for this output device.

The carriage control type of the file is embedded (none) carriage control.

RESPONSE

Implicit spooling is not a recommended method for submitting jobs to an output queue. Implicit spooling restricts the user to system defaults. The ability to specify job attributes, such as pagination (/FEED), is lost. The recommended method for submitting jobs to output queues under program control is the VAX/VMS Version 4.0 system service \$SNDJBC.

The \$SNDJBC system service is documented on pages 322 to 359 in the VAX/VMS System Services Reference Manual. This service provides greater control of the symbiont processing of the job.

OPERATING SYSTEM: VAX/VMS V4.0
PRODUCT: VAX/VMS
COMPONENT: PRINT SYMBIONT

Seq. 15.30.9

Print symbiont performs tab expansion

PROBLEM STATEMENT

The VAX/VMS Version 4.0 print symbiont does not allow horizontal tabs to be expanded by the device.

RESPONSE

When the output queue is started, the VAX/VMS Version 4.0 print symbiont determines if tab expansion is required by accessing the current device characteristics. The Version 4.0 print symbiont expands horizontal tabs only when the device is incapable of handling the tab character. On a device controlled by the LCDRIVER or LPDRIVER, the DCL command SET PRINTER/TAB sets the tab characteristic for that device. On a serial line controlled by the terminal driver, the DCL command SET TERMINAL/TAB sets the tab characteristic for that serial device.

The device characteristics for a particular output queue are determined at the start of that output queue. Therefore, set the device characteristics before starting the output queue. If the characteristics of a device need to be reset after the output queue has been started, stop the queue, reset the device characteristics, and then restart the output queue. The output queue must be completely stopped before changing any device characteristics.

We will consider enhancing the print symbiont to access the device characteristics more frequently.

OPERATING SYSTEM: VAX/VMS V4.1
PRODUCT: VAX/VMS
COMPONENT: PRINT SYMBIONT

Seq. 15.30.10

Print symbiont process termination

PROBLEM STATEMENT

The print symbiont exits with unexpected symbiont process termination and a symbiont process dump. The print symbiont exits on jobs with a block length of zero. The following error message is printed on the console log:

```
***** OPCOM  date-time *****  
Message from JOB_CONTROL  
%JBC-W-SYMDEL, unexpected symbiont process termination
```

```
***** OPCOM  date-time *****  
Message from JOB_CONTROL  
-SYSTEM-F-ACCVIO, access violation, reason mask=6E, virtual  
address=03000000, PC=00000000, PSL=2FFC0000
```

Deleting, aborting, and requeuing jobs occasionally causes the symbiont process to abort. The following error message is printed on the console log:

```
***** OPCOM  date-time *****  
Message from JOB_CONTROL  
%JBC-W-SYMDEL, unexpected symbiont process termination
```

```
***** OPCOM  date-time *****  
Message from JOB_CONTROL  
-PSM-F-BADLOGIC, internal logic error detected at PC 0000B46E
```

RESPONSE

There are two known problems which result in the unexpected symbiont process termination. One problem is associated with the creation of file name banner characters on file separation pages. This problem

only occurs when the current job contains no file identification. The second known problem is a result of an improper communication handshake between the job controller and the print symbiont.

Problem in the creation of file separation pages

If LOGINOUT receives an error when attempting to open a batch log file, a special job is sent to the print symbiont. This job contains no file identification. Instead, the job contains the error message returned to the job controller by LOGINOUT. If file separation pages are enabled in the VAX/VMS Version 4.0 print symbiont, and such a job is queued to a running output queue, the symbiont attempts to use the file identification when creating the file separation pages. An access violation results.

This problem is corrected in VAX/VMS Version 4.2. Deleting the offending print job and restarting the output queues controlled by this symbiont process will clear the problem. Rebooting with a new queue file is not necessary. As a temporary workaround, set the block limit on the output queues to print jobs with a block size from 1 to infinity. The following DCL command sets the block from 1 to infinity for the output queue FOO:

```
$ SET QUEUE /BLOCK_LIMIT=(1,"") FOO
```

Jobs with a block size of zero are retained in the queue. The system manager can either delete these jobs or turn off file separation pages and print the error messages.

Problem in the communication between the job controller and the print symbiont

In VAX/VMS Version 4.0, the print symbiont maintains an internal data structure for each output queue. This internal data structure is reset upon the arrival of each task (file to process). Arrival of tasks is controlled by a communication handshake between the job controller and the print symbiont. When the print symbiont receives a task, it resets the internal data structure, performs some initialization, and then responds to the job controller's start task message. Similarly, deletion of a task requires a response to the job controller's message.

If the symbiont receives a deletion message from the job controller during initialization but before responding to the job controller's start task message, the symbiont improperly responds to the deletion request before responding to the start task request. Internally, the

symbiont continues processing the task until the task can be cleanly aborted. The job controller, on the other hand, schedules any pending task for processing. If the symbiont is still processing the aborted task, it resets its internal data structure upon receipt of the second task. Since this data structure maintains all the state information for the current task, resetting this data structure creates unpredictable results. Subsequently, the symbiont may either abort with a dump or loop internally.

This problem is corrected in VAX/VMS Version 4.2. In the meantime, avoid issuing delete, abort or requeue requests while the print symbiont process is starting, stopping, or aborting a job.

OPERATING SYSTEM: VAX/VMS V4.1
PRODUCT: VAX/VMS
COMPONENT: PRINT SYMBIONT

Seq. 15.30.11

Print symbiont enters compute loop

PROBLEM STATEMENT

1. The print symbiont enters a compute loop after a paused output queue is started. The output queue paused near the end of the job.
2. If a queue is in a paused state and the operator issues the DCL command START/QUEUE/BACKWARD=n, where n is greater than the current page position, the print symbiont process enters a compute loop.

RESPONSE

Both of these problems are resolved in VAX/VMS Version 4.2.

Please avoid any attempts to pause an output queue near the end of the job. Attempting to pause the output queue, when a small print job is executing or attempting to position at or near the end of the job, is especially prone to initiating print symbiont process looping. Also avoid operator commands which may position the output queue before the first page of the job.

If the print symbiont process enters a compute loop, determine the print symbiont process identification. Then issue the DCL command:

```
$ STOP/IDENTIFICATION=symbiont_process_id
```

Privileges are required to stop the print symbiont process. All output queues controlled by this symbiont process must be restarted after deletion of the looping process.

OPERATING SYSTEM: VAX/VMS V4.1
PRODUCT: VAX/VMS
COMPONENT: PRINT SYMBIONT

Seq. 15.30.12

Miscellaneous problems in print symbiont

PROBLEM STATEMENT

In VAX/VMS Version 4.0, the following formatting and nuisance problems have been identified:

1. There are problems with vertical tab, bolding, and underlining when the left margin is nonzero.
2. When the VAX/VMS Version 4.0 DCL command PRINT /NOFLAG /HEADER is issued, the header is not printed on the first page of the first copy.
3. Failure to cancel CTRL/O results in all jobs submitted to the controlling queue to be lost until a subsequent CTRL/O is issued on the device.
4. There is improper termination of escape sequences. This causes data embedded in an escape sequence to be improperly interpreted.
5. An extra blank line is generated on paper when the bottom margin is nonzero and /FEED is enabled.
6. No flag page is printed when the burst page is requested. Multiple rows of burst characters are not printed on the perforation between the flag page and burst separation pages.

RESPONSE

These problems are corrected in VAX/VMS Version 4.2.

OPERATING SYSTEM: VAX/VMS V4.0
PRODUCT: VAX/VMS
COMPONENT: PRINT SYMBIONT

Seq. 15.30.13

Serial printers on DMF disconnect

PROBLEM STATEMENT

Printers on the serial lines of the DMF-32 often disconnect. This presents problems on output queues controlling the serial line; jobs might be lost or corrupted. The terminal line is set /NODMA.

RESPONSE

There is a problem in the DMF-32 driver with regard to device timeouts. An incorrect algorithm is used to calculate the amount of time to wait for the I/O to complete. The amount of time calculated is abnormally small. If the terminal sends an XOFF at the "right" time, the device might time out. If this terminal is in use as a printer, then upon timeout, the current job aborts. Subsequently, the following error message is sent to the output device by the print symbiont:

```
%PSM-E-WRITEERR, error writing TXA0  
-SYSTEM-F-TIMEOUT, device timeout
```

We expect to fix this problem in a future update of VAX/VMS. As a temporary workaround, set the terminal /DMA. This avoids using the incorrect timeout value. The following DCL command sets this attribute for the terminal TXA0:.

```
$ SET TERMINAL TXA0: /DMA
```


OPERATING SYSTEM: VAX/VMS V4.0
PRODUCT: VAX/VMS
COMPONENT: DCL

Seq. 20.5.1

Captive account causes LOGINOUT access violation

PROBLEM
STATEMENT

A captive account, which cannot access its login command file, causes an access violation in LOGINOUT.

RESPONSE

This problem is fixed in VAX/VMS Version 4.2.

OPERATING SYSTEM: VAX/VMS V4.0
PRODUCT: VAX/VMS
COMPONENT: DCL

Seq. 20.5.2

Cannot change/examine logical name table prot

PROBLEM
STATEMENT

VAX/VMS Version 4.0 allows protection masks to be specified when creating a logical name. However, there is no corresponding capability to change and/or examine the protection assigned to a table.

RESPONSE

The ability to examine the current protection mask of a logical name table is provided in VAX/VMS Version 4.2.

The ability to change the protection mask of an existing logical name table will be considered for implementation in a future release of VAX/VMS.

OPERATING SYSTEM: VAX/VMS V4.0
PRODUCT: VAX/VMS
COMPONENT: DECnet

Seq. 25.5.5

STREAM_LF file transfer hangs to non-VMS partners

PROBLEM STATEMENT

An attempt to access a file having STREAM_LF format using DECnet sometimes results in the process hanging if the remote node is not a VAX/VMS system.

RESPONSE

This behavior is caused by a failure in the error recovery logic within RMS. This logic performs the various message traffic necessary to recover from a reported error during a file transfer. The logic contains an error which produces an invalid error recovery message and typically results in both partners waiting for an input message.

This problem was corrected in VAX/VMS Version 4.1.

OPERATING SYSTEM: VAX/VMS V4.1
PRODUCT: VAX/VMS
COMPONENT: DECnet

Seq. 25.5.6

DECnet gives incorrect error on invalid user name

PROBLEM
STATEMENT

If an invalid user name is used in a DECnet access control string, the error returned is SS\$_LINKEXIT instead of SS\$_INVLOGIN.

RESPONSE

This problem is fixed in VAX/VMS Version 4.2.

OPERATING SYSTEM: VAX/VMS V4.0
PRODUCT: VAX/VMS
COMPONENT: DDDRIVER

Seq. 31.10.1

TU58 times out when /DATA_CHECK=WRITE is used

PROBLEM STATEMENT

When a TU58 cartridge is mounted using the /DATA_CHECK=WRITE qualifier for the DCL command MOUNT, timeout errors occur on subsequent write operations if the I/O operation crosses a track boundary. This occurs when using the CONSCOPY utility to make a duplicate copy of the console TU58 on a VAX-11/730 or a VAX-11/750, but can occur under other circumstances as well.

RESPONSE

The root of the problem is that the default timeout value for I/O operations performed by the TU58 device driver is only long enough to accommodate one complete traverse of the tape.

The TU58 is a block-addressable tape device, which logically appears to consist of four tracks of 128 blocks each. When a track boundary is crossed during a read or write operation, the tape must be rewound to the beginning before the operation can continue.

However, when a write data-check is performed, the tape must be positioned to the beginning of the data which was just written. If this data straddles a track boundary, a second traverse of the tape is required.

In a future update of VAX/VMS, we expect to correct this problem by increasing the timeout value if a data-checked I/O operation is being performed.

In the meantime, avoid using the /DATA_CHECK=WRITE qualifier. Note also that the status of the error returned by EXCHANGE during a CONSCOPY operation is "informational" rather than "fatal" indicating that EXCHANGE has recovered from the error.

OPERATING SYSTEM: VAX/VMS V4.0
PRODUCT: VAX/VMS
COMPONENT: EDIT/ACL

Seq. 35.5.1

EDIT/ACL deletes ACE granting access

PROBLEM STATEMENT

If a user has gained control access to a file via the access control list (ACL), using the ACL editor to modify the ACL results in a privilege error at the end of the editing session. In addition, the ACL for the file is deleted.

RESPONSE

This problem is a result of the way the ACL editor writes the modified ACL back to the file. First, the entire ACL is deleted so that the new version can be written. However, if access to the file is gained via an access control list entry (ACE), the ACE granting access is deleted. When the attempt is made to write out the new ACL, the user does not have the necessary privileges because the ACE has been deleted.

We expect this problem to be corrected in a future update of VAX/VMS.

OPERATING SYSTEM: VAX/VMS V4.0
PRODUCT: VAX/VMS
COMPONENT: EDIT/ACL

Seq. 35.5.2

Problem in refresh logic causes access violation

PROBLEM
STATEMENT

After doing about six successive refresh (Gold + CTRL/R) operations, the ACL editor fails with an access violation.

RESPONSE

This problem is fixed in VAX/VMS Version 4.2.

OPERATING SYSTEM: VAX/VMS V4.0
PRODUCT: VAX/VMS
COMPONENT: EDIT/ACL

Seq. 35.5.3

Missing status return

PROBLEM
STATEMENT

If the user is able to read a file's access control list (ACL), but does not have the necessary privileges to change it, the ACL editor will exit with a success status when ending an editing session.

RESPONSE

This problem is fixed in VAX/VMS Version 4.2.

OPERATING SYSTEM: VAX/VMS V4.0
PRODUCT: VAX/VMS
COMPONENT: CONVERT

Seq. 40.5.3

CONVERT incorrectly returns RTL error

PROBLEM STATEMENT

When converting input files with fixed-length records, CONVERT might report the following error, even though the records are the correct length:

%CONVERT-I-RTL, record longer than maximum length

RESPONSE

This behavior occurs because CONVERT computes unnecessarily large buffer sizes.

We expect that this problem will be fixed in a future update of VAX/VMS. As a workaround, specify the /TRUNCATE qualifier on the CONVERT command. Note that the addition of this qualifier does not affect the validity or structure of the output file, but allows CONVERT to process the file successfully.

OPERATING SYSTEM: VAX/VMS V4.0
PRODUCT: VAX/VMS
COMPONENT: RMS

Seq. 40.45.6

File corruption with global buffers

PROBLEM STATEMENT

Periodically, RMS bucket format check failures occur on a number of shared files.

RESPONSE

This problem is fixed in VAX/VMS Version 4.2. In the meantime, disabling global buffers from the file should provide a temporary workaround.

OPERATING SYSTEM: VAX/VMS V4.0
PRODUCT: VAX/VMS
COMPONENT: RMS

Seq. 40.45.7

SYS\$RMSRUNDWN returns incorrect status

PROBLEM
STATEMENT

SYS\$RMSRUNDWN fails to return the status of RMS\$_NORMAL on successful completion of the service. The documentation states that SYS\$RMSRUNDWN should be repeatedly called until the value RMS\$_NORMAL is returned.

RESPONSE

The success path out of SYS\$RMSRUNDWN corrupts the value of R0. At the moment, it is impossible to receive this return value; the call returns an alternate success code of either SS\$_WASSET or SS\$_WASCLR.

This behavior is corrected in VAX/VMS Version 4.2.

OPERATING SYSTEM: VAX/VMS V4.0
PRODUCT: VAX/VMS
COMPONENT: RMS

Seq. 40.45.8

Search list questions

PROBLEM STATEMENT

Unexpected behavior is observed with search lists. First, the DCL command CREATE/DIRECTORY creates directories in the last translation of a search list. Second, RMS produces RMS-E-DNF errors when it attempts to find a nonexistent file in a search list.

RESPONSE

The first problem, concerning the behavior of CREATE/DIRECTORY, was corrected in VAX/VMS Version 4.1. It creates the directories in the first translation of a search list.

The second behavior is correct. This becomes more apparent when considering that a search list specifically defines a set of places. RMS assumes that if a specific set of places is defined, they all exist; it cannot do otherwise. The RMS-E-DNF errors are returned because RMS is told to look in a set of directories, some of which do not exist.

OPERATING SYSTEM: VAX/VMS V4.0
PRODUCT: VAX/VMS
COMPONENT: RMS

Seq. 40.45.9

Remote command procedures fail

PROBLEM STATEMENT

Execution of a remote command procedure fails if it invokes an image. As an example, given a command procedure, B.COM, consisting of the lines:

```
$ RUN FOO
$ DIRECTORY
$ EXIT
```

the DCL command:

```
@A::B
```

fails with the error:

```
%DCL-W-SKPDAT, image data (records not beginning with "$")
ignored.
```

RESPONSE

VAX/VMS Version 4.0 RMS contains an error which causes it to fail to detect the end of image data in a remote command procedure. As a result, whenever a remote command procedure invokes an image, RMS proceeds to read the entire command file before reporting an end-of-file condition to DCL. This causes DCL to report erroneously that image data is skipped. Also, DCL does not attempt to execute any further lines in the command procedure.

This problem was corrected in VAX/VMS Version 4.1.

OPERATING SYSTEM: VAX/VMS V4.1
PRODUCT: VAX/VMS
COMPONENT: RMS

Seq. 40.45.10

Version 4 COPY will not copy Version 3 ISAM files

PROBLEM STATEMENT

Attempts to copy certain RMS ISAM files created on a VAX/VMS Version 3 system to a VAX/VMS Version 4 system fail with the following message:

%COPY-W-INCOMPAT, input and output have incompatible attributes

RESPONSE

This problem occurs as a result of the interaction of RMS and COPY. COPY objects to the input file because the maximum bucket size in the file header is larger than any of the buckets actually in the file. VAX/VMS Version 3 RMS allowed ISAM files to be created this way.

VAX/VMS Version 4 RMS creates the output file with a maximum bucket size that truly reflects the maximum bucket size of any area in the file, and COPY notices the difference.

At this time, there are no plans to modify this behavior. As a workaround, use CONVERT from the VAX/VMS Version 4 system to produce a file with a valid maximum bucket size in the file header:

```
$ CONVERT V3SYS::disk:[dir]file.dat *
```

Alternatively, use EDIT/FDL to set the BUCKET_SIZE secondary under the FILE primary to be the maximum of all of the BUCKET_SIZE values under the AREA n primaries.

A subsequent CONVERT/FDL of the file on the VAX/VMS Version 3 system yields a valid file that can then be transferred successfully using COPY. See the VAX/VMS File Definition Language Facility Reference Manual for more details on using EDIT/FDL, as well as further information on the structure of FDL files.

OPERATING SYSTEM: VAX/VMS V4.0
PRODUCT: VAX/VMS
COMPONENT: RMS

Seq. 40.45.11

RMS file parse problem with level 8 directories

PROBLEM STATEMENT

The following command sequence fails on VAX/VMS Version 4.0:

```
$ SET DEFAULT DISK1:[A.B.C.D.E.F.G.H]  
$ DIRECTORY SYS$DISK:[]  
%RMS-F-DIR, error in directory name
```

RESPONSE

When RMS attempts to parse a file name that contains an empty directory element, it temporarily includes this null directory as a directory level in the file name. Since this occurs after the default directory string has been applied, default directories that already contain eight elements fail with RMS-F-DIR.

We expect to correct this behavior in a future update of VAX/VMS. Until then, this problem is easily avoided by not specifying the null directory string in the file names and allowing RMS to fill this field in as the final step to file name processing.



OPERATING SYSTEM: VAX/VMS V4.0
PRODUCT: VAX/VMS
COMPONENT: AUTHORIZE

Seq. 55.10.3

Clarification of ADD/NETWORK

PROBLEM STATEMENT

When attempting to specify access limits on users by using AUTHORIZE, the following command denies all access:

```
UAF> ADD JOE /NETWORK/NOINTERACTIVE/NOBATCH
```

Is it possible to insure that only NETWORK access is granted?

RESPONSE

The above command is incorrectly parsed by AUTHORIZE, and all access is denied.

In VAX/VMS Version 4.2, this behavior is fixed so that the command executes properly and allows only NETWORK access.

OPERATING SYSTEM: VAX/VMS V4.0
PRODUCT: VAX/VMS
COMPONENT: AUTHORIZE

Seq. 55.10.4

AUTHORIZE and DISKQUOTA do not return status

PROBLEM
STATEMENT

For ease of command procedure use, utilities such as AUTHORIZE and DISKQUOTA should be enhanced to support foreign command line interfaces; they should return the status of each invocation in the symbol \$STATUS.

RESPONSE

AUTHORIZE presently has a foreign command interface. The correct status is returned in VAX/VMS Version 4.2.

DISKQUOTA does not presently have a foreign command interface, but we will consider adding one which returns status for a future release of VAX/VMS.

OPERATING SYSTEM: VAX/VMS V4.0
PRODUCT: VAX/VMS
COMPONENT: AUTHORIZE

Seq. 55.10.5

Problem with SHOW/ID followed by MOD/ID

PROBLEM STATEMENT

The MODIFY/IDENTIFIER command fails when preceded by the following SHOW/IDENTIFIER command.

```
UAF> modify/identifier GUSTAV_MAHLER /attribute=resource
%UAF-I-RDBMDFYMSG, identifier GUSTAV_MAHLER modified
UAF> show/identifier GUSTAV_MAHLER
      Name                Value                Attributes
  GUSTAV MAHLER          %X80010029          RESOURCE
UAF> modify/identifier GUSTAV_MAHLER /attribute=resource
%UAF-E-RDBMDFYERR, unable to modify identifier GUSTAV_MAHLER
-SYSTEM-F-IVIDENT, invalid identifier format
```

Also, the MODIFY/IDENTIFIER/HOLDER command fails in all contexts.

```
UAF> modify/identifier/holder=JOE GUSTAV_MAHLER /attribute=resource
%UAF-E-RDBMDFYERR, unable to modify identifier GUSTAV_MAHLER
-SYSTEM-F-IVIDENT, invalid identifier format
```

RESPONSE

Improper coding in the MODIFY/IDENTIFIER logic causes the working parameters to be set up incorrectly under these circumstances.

Both of these problems are corrected in VAX/VMS Version 4.2.

OPERATING SYSTEM: VAX/VMS V4.0
PRODUCT: VAX/VMS
COMPONENT: DEBUG

Seq. 55.50.1

SET MODULE command takes too long

PROBLEM STATEMENT

The DEBUG command:

```
DEBUG> SET MODULE V40SHR
```

where V40SHR is an 18000 block shareable image module supplied by the user, takes over 2 hours elapsed time to complete.

RESPONSE

When DEBUG executes the SET MODULE command, it reads the global symbol table in the shareable image and builds an internal table of symbols that is sorted by address. The time required for the Version 4.0 sorting algorithm is proportional to N^2 , where N is the number of symbols in the module.

In VAX/VMS Version 4.2, the sorting code uses an algorithm which is proportional to $N(\log N)$. As a result, it takes approximately 20 seconds of CPU time to perform the same SET MODULE command.

OPERATING SYSTEM: VAX/VMS V4.1
PRODUCT: VAX/VMS
COMPONENT: DEBUG

Seq. 55.50.2

Comma lists on DEPOSIT not allowed

PROBLEM STATEMENT

Under VAX/VMS Version 3.n, a user could perform the following command, which would deposit the specified values into successive locations:

DBG> DEPOSIT 200=1,2,3

Under VAX/VMS Version 4, the above command produces a syntax error response. The documentation implies this feature should still work. The HELP text does not show this syntax.

RESPONSE

Large portions of VAX DEBUG have been rewritten for VAX/VMS Version 4. The current implementation does not allow successive deposits from a single DEPOSIT command. However, the documentation for the DEPOSIT command has not been changed to reflect the new behavior.

In a future revision, the documentation of the DEPOSIT command will be corrected to reflect the current behavior.

OPERATING SYSTEM: VAX/VMS V4.0
PRODUCT: VAX/VMS
COMPONENT: LINKER

Seq. 56.20.3

Version 4.0 images larger than Version 3.0 images

PROBLEM STATEMENT

The size of image files linked on VAX/VMS Version 4.0 can be substantially larger than those linked before VAX/VMS Version 4.0.

RESPONSE

When the linker produces an image that has several consecutive uninitialized pages, it creates an image section descriptor in the image header that describes these pages, which are called demand-zero pages. This prevents the uninitialized pages from occupying disk space and results in a smaller image file. When the image is later executed, the image activator interprets this image section descriptor and marks these pages as demand-zero in the process' address space.

However, these additional demand-zero image sections incur additional image activator overhead, since they must be treated individually. This is usually not a problem, but images with a large number of images sections incur excessive image activator overhead when run. Because of trade-offs such as these, the linker provides a number of parameters which can be set by the user, but have defaults that are usually adequate.

When the linker surpasses 96 (default value) image sections during the production of an image, it puts a priority on minimizing the number of additional image sections. This is done by disabling the demand-zero optimization mentioned above. Note that this can result in a larger image file, since each uninitialized image page has a corresponding disk block.

This is the intended behavior, but it is easily controlled. The parameter `ISD_MAX` (see the VAX/VMS Linker Reference Manual, page LINK-24) controls the upper limit on image section creation before demand-zero compression is disabled. The number of image sections in an image is listed on the last page of the linker map. Set `ISD_MAX` to some value greater than the number of image sections.

The occurrence of this problem is made more likely by the breakup of the VAX/VMS Run-Time Library (VMSRTL), especially if the image file contained almost 96 image sections before VAX/VMS Version 4.0. If the image file references more than one of the individual shareable images that now comprise VMSRTL, more image sections are added to the image file than were added before VAX/VMS Version 4.0.

OPERATING SYSTEM: VAX/VMS V4.0
PRODUCT: VAX/VMS
COMPONENT: MAIL

Seq. 56.30.1

MAIL cannot run on a GIGI terminal

PROBLEM
STATEMENT

MAIL will not activate on a GIGI terminal and no error messages are produced.

MAIL uses the SMG screen management package, which does not support GIGI terminals.

RESPONSE

In VAX/VMS Version 4.2, MAIL displays an error message for undefined terminals.

In addition, SMG includes GIGI support in VAX/VMS Version 4.2.

Thus, starting with VAX/VMS Version 4.2, it will be possible to run MAIL on a GIGI terminal.

OPERATING SYSTEM: VAX/VMS V4.0
PRODUCT: VAX/VMS
COMPONENT: MONITOR

Seq. 56.40.1

Foreign terminal support does not work

PROBLEM
STATEMENT

MONITOR works improperly on foreign terminals.

RESPONSE

The MONITOR utility shipped with VAX/VMS Version 4.0 uses the RTL screen package (SCR\$...) which is documented in the VAX/VMS Release Notes, Version 4.0 under the "Obsolete RTL Routines." Foreign terminals are supported with this screen package through the use of the SYS\$EXAMPLES:SCRFT.MAR program. This program must be modified to handle the needs of a foreign terminal. All of the information necessary for doing this is contained within SCRFT.MAR.

Because of a problem with the RTL screen package's handling of virtual memory, the foreign terminal support does not work in VAX/VMS Versions 4.0 and 4.1.

This problem is fixed in VAX/VMS Version 4.2.

OPERATING SYSTEM: VAX/VMS V4.0
PRODUCT: VAX/VMS
COMPONENT: MONITOR

Seq. 56.40.2

MONITOR's virtual memory usage grows continuously

PROBLEM
STATEMENT

MONITOR's virtual memory size continuously increases. If a process runs MONITOR for a sufficient length of time, it eventually terminates with an insufficient virtual memory error.

RESPONSE

This problem is caused by the screen management package which MONITOR uses for display. Under certain circumstances, the screen management package does not free up the same amount of virtual memory which it allocated. In this case, the amount freed is less than the amount allocated, which causes the continuous growth in virtual memory usage and eventually the insufficient virtual memory error.

This problem is fixed in VAX/VMS Version 4.2.

OPERATING SYSTEM: VAX/VMS V4.0
PRODUCT: VAX/VMS
COMPONENT: PURGE

Seq. 56.52.1

PURGE can incorrectly delete files

PROBLEM
STATEMENT

If a file specification appears twice in a PURGE command line, all versions of the file are deleted. For example, when a user issues the following command, all versions of FOO.BAR are deleted:

```
$ PURGE FOO.BAR,FOO.BAR
```

RESPONSE

This problem is fixed in VAX/VMS Version 4.2.

OPERATING SYSTEM: VAX/VMS V4.0
PRODUCT: VAX/VMS
COMPONENT: SET

Seq. 56.80.2

Volume retention dates override SET FILE dates

PROBLEM
STATEMENT

Under VAX/VMS Version 3, it was possible to reset the expiration date of a file to any date, without regard to the date set by having volume retention enabled. This is no longer the case with VAX/VMS Version 4.0.

RESPONSE

We expect this problem to be corrected in a future update of VAX/VMS.

OPERATING SYSTEM: VAX/VMS V4.1
PRODUCT: VAX/VMS
COMPONENT: SET PASSWORD

Seq. 56.80.3

SET PASSWORD always returns success status

PROBLEM
STATEMENT

The DCL command SET PASSWORD returns SS\$ _NORMAL in \$STATUS, regardless of the success or failure of the command.

RESPONSE

This behavior is fixed in VAX/VMS Version 4.2.

OPERATING SYSTEM: VAX/VMS V4.1
PRODUCT: VAX/VMS
COMPONENT: SHOW CLUSTER

Seq. 56.85.1

CNX_STATE documentation error

PROBLEM STATEMENT

The SHOW CLUSTER utility displays the value NEW for the CNX_STATE of the MEMBERS class. The description for NEW states:

The system has just booted and the state of the connection is too new to be determined.

No other value for this field has been seen on the local CPU.

RESPONSE

The status value of NEW for the connection state field, CNX_STATE, as described in the VAX/VMS Show Cluster Utility Reference Manual, page SHCL-27, is incorrect.

We expect to correct this documentation error in a future release of VAX/VMS. The correct description for the value NEW should be:

No attempt to make a connection has been made yet.

NEW is the correct status value for the local node. The Connection Manager does not attempt to form a VAXcluster connection to itself on the local node.

Note that the description of the NEW value for the CNX_STATE field is correct in SHOW CLUSTER's online HELP. HELP for the CNX_STATE field can be obtained by invoking SHOW CLUSTER with the /CONTINUOUS qualifier and typing HELP FIELD CNX_STATE.

OPERATING SYSTEM: VAX/VMS V4.0
PRODUCT: VAX/VMS
COMPONENT: SHUTDOWN

Seq. 56.90.1

SHUTDOWN\$INFORM_NODES usage described

PROBLEM STATEMENT

When the orderly system shutdown procedure, SYSS\$SYSTEM:SHUTDOWN.COM, is run, all users running on all VAXcluster members receive notification of the system shutdown. This might cause users to log out, assuming that the node they are using is shutting down. However, this is often not the case.

The orderly system shutdown procedure appears to have code to notify users of a system shutdown using the REPLY /NODE= command, but it does not work correctly.

RESPONSE

The REPLY /NODE= option in the orderly system shutdown is activated by defining the process logical name SHUTDOWN\$INFORM_NODES before invoking the shutdown procedure. For example, the command sequence:

```
$ DEFINE SHUTDOWN$INFORM_NODES MOE,LARRY  
$ @SYSS$SYSTEM:SHUTDOWN
```

will cause only the users on VAXcluster members MOE and LARRY to be informed of the system shutdown. We recognize that this feature is not described in any VAX/VMS documentation, and we will attempt to remedy that oversight as soon as possible.

The primary considerations for the default orderly system shutdown behavior are twofold. First, a user logged into any VAXcluster member might be affected by the shutting down of any other VAXcluster member. The user might have batch jobs running on the other VAXcluster member or, if terminal servers are in use, the user might have an alternate terminal session active on the VAXcluster member that is being shut down.

Therefore, we believe all users on all VAXcluster members must be informed of the shutdown of any VAXcluster member. Second, all orderly shutdown messages include the name of the VAXcluster member being shut down. A user need only check the shutdown message carefully to avoid logging out of a system unnecessarily.

OPERATING SYSTEM: VAX/VMS V4.0
PRODUCT: VAX/VMS
COMPONENT: SHUTDOWN

Seq. 56.90.2

Time-of-year clock causes SHUTDOWN error

PROBLEM STATEMENT

Occasionally, during an orderly system shutdown, the SYS\$SYSTEM:SHUTDOWN command procedure exits quickly with the following error messages:

%SET-E-NOTSET, error modifying time
-SYSTEM-F-IVTIME, invalid time

However, a SHOW TIME command performed immediately after the error occurs always shows the correct time. The problem can be corrected by performing one or more SET TIME commands specifying the current time.

RESPONSE

We believe this problem results from an improperly functioning time-of-year hardware clock. VMS maintains the time of day using two clocks. While the system is running, a memory quadword is updated at 10-millisecond intervals. This is the quadword current system time discussed in the descriptions of VMS time-related system services. In addition, most VAX processors provide a time-of-year clock in hardware, which maintains the current time when the processor is not operating. The time-of-year clock allows VMS to "know" the correct time whenever it is booted. When no time parameter is specified, as is the case during an orderly system shutdown, the SET TIME command recalibrates the memory quadword time using the time-of-year hardware clock.

The "invalid time" error is produced by the recalibrate function. This happens whenever the recalibrate function determines that the quadword current system time is more than 1 day ahead of the time given by the time-of-year clock. Executing a SET TIME command that specifies the current time before performing the orderly system shutdown eliminates the error; this causes VMS to reset the time-of-year clock.

An error might occur if the time-of-year clock has lost a day or more since the last time the system was booted or the last time a SET TIME command was executed, whichever occurred more recently.

In addition, to eliminate the errors mentioned above, we are considering changing the way that the orderly system shutdown command procedure uses the SET TIME command.

OPERATING SYSTEM: VAX/VMS V4.0
PRODUCT: VAX/VMS
COMPONENT: SPAWN

Seq. 57.10.1

Cannot specify spooled device with SPAWN

PROBLEM
STATEMENT

Spawning by using either the DCL SPAWN command or the LIB\$SPAWN routine fails when the explicitly specified output stream is a spooled device.

RESPONSE

This problem is fixed in VAX/VMS Version 4.2.

OPERATING SYSTEM: VAX/VMS V4.0
PRODUCT: VAX/VMS
COMPONENT: SPAWN

Seq. 57.10.2

LIB\$SPAWN fails with MBFULL

PROBLEM STATEMENT

When LIB\$SPAWN is invoked with RESOURCE_WAIT disabled, on a heavily loaded system, it returns an error status:

%SYSTEM-W-MBFULL, mailbox is full

When the system is lightly loaded, the call to LIB\$SPAWN is successful. Increasing the system default mailbox size also rectifies the error.

RESPONSE

While not documented in the VAX/VMS Run-Time Library Routines Reference Manual under LIB\$SPAWN, the VAX/VMS DCL Dictionary states on page DCL-745 that one of the restrictions governing a SPAWN operation is the requirement that RESOURCE_WAIT mode be enabled for the process. This is also documented in the VAX/VMS System Messages and Recovery Procedures Reference Manual on page 2-295, where it discusses the MBFULL error message.

To insure that LIB\$SPAWN does not incur the MBFULL error, enable RESOURCE_WAIT for the process via the SET PROCESS/RESOURCE_WAIT command. This synchronizes the mailbox I/O between the parent process and the subprocess. Increasing the system default mailbox size only masks the problems, allowing a greater system load before exhibiting the MBFULL error condition.

OPERATING SYSTEM: VAX/VMS V4.1
PRODUCT: VAX/VMS
COMPONENT: DOCUMENTATION

Seq. 65.5.4

SYS\$GETJPI documentation errors

PROBLEM
STATEMENT

Page SYS-198 of the VAX/VMS System Services Reference Manual indicates that the symbols JPI\$ OTHER, JPI\$ NETWORK, JPI\$ BATCH, and JPI\$ INTERACTIVE are defined in the library module \$JPIDEF. These symbols are documented incorrectly; they should all have a "K" inserted in their names (for example, JPI\$K_OTHER, JPI\$K_NETWORK, etc.).

RESPONSE

The four symbols that appear in the table at the top of page SYS-198 should have a "K" in their names. This is to distinguish these symbols, return values for the JPI\$ MODE item, from item codes whose names are of the form JPI\$_item-code.

These errors are corrected in the documentation for VAX/VMS Version 4.2.

OPERATING SYSTEM: VAX/VMS V4.0
PRODUCT: VAX/VMS
COMPONENT: DOCUMENTATION

Seq. 65.5.5

SYS\$GETJPI documentation error

PROBLEM
STATEMENT

The JPI\$_IMAGNAME item code of the \$GETJPI system service is incorrectly documented.

When the JPI\$_IMAGNAME item code is specified, \$GETJPI does not return an 8-byte character-string descriptor that points to the name of the current image file. Instead, it returns the name itself in the buffer specified in the item list.

RESPONSE

This item code description is corrected in the documentation for VAX/VMS Version 4.2.

OPERATING SYSTEM: VAX/VMS V4.0
PRODUCT: VAX/VMS
COMPONENT: DOCUMENTATION

Seq. 65.5.6

CHAN argument incorrect for \$GETDVI

PROBLEM
STATEMENT

The description of the CHAN argument for \$GETDVI is incorrect. The CHAN argument of the \$GETDVI service is passed by value instead of by reference as stated in the VAX/VMS System Services Reference Manual.

RESPONSE

The correction will be reflected in a future revision of the documentation.



•

•



•

•



REPUBLISHED ARTICLES



•

•



•

•



REPUBLISHED ARTICLES

The following articles are being republished to correct inaccuracies. Five articles for RMS and two articles for CONVERT have been resequenced to reflect the new components numbering system. The technical information in these articles remains unchanged, however, there are minor editorial changes.

OPERATING SYSTEM: VAX/VMS V4.0
PRODUCT: VAX/VMS
COMPONENT: CONVERT

Seq. 40.5.1

CONVERT/RECLAIM may access violate

PROBLEM STATEMENT

When attempting to perform a CONVERT/RECLAIM on an RMS ISAM file, an access violation occurs. The file is large, yet very sparsely populated as a result of many record deletions.

RESPONSE

The index structure of the file is corrupt. However, we believe that CONVERT/RECLAIM should be able to determine that the data it is processing is incorrect. We expect to enhance CONVERT/RECLAIM to be more robust in a future update of VAX/VMS.

A file corrupted in this manner can be recovered by issuing a CONVERT command such as:

```
$ CONVERT OLD.DAT NEW.DAT
```

This will produce a fresh version of the file, although it will be considerably smaller than the original file because of the scarcity of records in OLD.DAT. In order to preallocate space for the new file to allow for the eventual insertion of more records, use an FDL file which describes the eventual size of the file. EDIT/FDL provides an easy method to specify these parameters.

OPERATING SYSTEM: VAX/VMS V4.0
PRODUCT: VAX/VMS
COMPONENT: CONVERT

Seq. 40.5.2

CONVERT can incorrectly report DUP and SEQ errors

PROBLEM
STATEMENT

CONVERT mistakenly complains about segmented keys being out of order when creating a Prolog 1 or 2 ISAM file.

RESPONSE

CONVERT compares segment-by-segment, even if an earlier segment showed the current key to be greater than the previous key. Since all key segments are extracted and concatenated for Prolog 3 files, this problem can be avoided by using Prolog 3 files.

We expect to correct this problem in a future update of VAX/VMS.

OPERATING SYSTEM: VAX/VMS V4.0
PRODUCT: VAX/VMS
COMPONENT: RMS

Seq. 40.45.1

Read from SYS\$OUTPUT fails

PROBLEM
STATEMENT

With VAX/VMS Version 4.0, the user cannot read from SYS\$OUTPUT. A FORTRAN program, such as the following:

```
READ (6,*) VALUE  
END
```

fails with the error message:

```
%FOR-F-ERRDURREA, error during read  
unit 6 file SYS$OUTPUT:.;  
user PC 00000412  
-RMS-F-FAC, record operation not permitted by  
specified file access (FAC)
```

RESPONSE

VAX/VMS Version 4.0 only allows writes to SYS\$OUTPUT (instead of reads and writes, as in previous versions of VAX/VMS) because it is enforcing that the stream is meant for output. Previous versions of VAX/VMS incorrectly allowed reads from SYS\$OUTPUT (and writes to SYS\$INPUT).

However, since many existing programs depend on this capability, the old behavior is restored in VAX/VMS Version 4.2.

OPERATING SYSTEM: VAX/VMS V4.0
PRODUCT: VAX/VMS
COMPONENT: RMS

Seq. 40.45.2

COPY/OVERLAY fails if destination write-protected

PROBLEM STATEMENT

COPY/OVERLAY does not work if the destination file is located on a remote node and the specified version number already exists. Instead of copying the data from the source file to the destination, COPY produces the following error message:

```
%COPY-E-OPENOUT, error opening NODE::FILE.EXT;1 as output"
-RMS-E-FEX, file already exists, not superseded"
```

RESPONSE

If a file is protected against write access by the network accessor, an access conflict occurs. If a file is available for write access, the COPY/OVERLAY operation succeeds with no errors. If the destination is protected against the write access request, the operation fails, since the COPY utility uses the create-if option when the /OVERLAY qualifier is specified. For DECnet file operations, this option is simulated within RMS as an \$OPEN or "on-error" \$CREATE sequence. This simulation is attempting the \$CREATE under circumstances other than the definition of create-if allowed. For instance, if the destination file is locked against write access, RMS incorrectly attempts to create a new file. Since the version in question already exists, the \$CREATE operation then fails with the error:

```
"-RMS-E-FEX, file already exists, not superseded"
```

In VAX/VMS Version 4.2, RMS returns the correct error from the \$OPEN and does not attempt to create a new file.

OPERATING SYSTEM: VAX/VMS V4.0
PRODUCT: VAX/VMS
COMPONENT: RMS

Seq. 40.45.3

Confusion on \$CREATE using search lists

PROBLEM STATEMENT

An attempted file creation fails when the destination directory is not located using the first translation of a search list.

Attempting, for example, to create:

SYS\$SYSROOT:[SYSMGR.MGRUTIL]FOO.BAR

fails if SYS\$SYSROOT is defined as a search list of \$1\$DUA21:[SYS7.],
SYS\$COMMON:, where SYS\$COMMON is \$1\$DUA21:[SYS7.SYSCOMMON.] and the
destination directory is SYS\$COMMON:[SYSMGR.MGRUTIL].

RESPONSE

The RMS \$CREATE service does not attempt to explore a search list fully. Instead, it only attempts to create new files using the first translation of any search list logical name that it encounters. In the example, the first translation of the destination (\$1\$DUA21:[SYS7.SYSMGR.MGRUTIL]) did not exist.

This behavior is documented in the VAX Record Management Services Reference Manual on page RMS-40.

OPERATING SYSTEM: VAX/VMS V4.0
PRODUCT: VAX/VMS
COMPONENT: RMS

Seq. 40.45.4

RENAME returns incorrect error message

PROBLEM
STATEMENT

For VAX/VMS Version 4.0, the RMS \$RENAME service returns the following error when the file to be renamed does not exist:

%RMS-E-ACC, ACP file access failed

Prior to VAX/VMS Version 4.0, \$RENAME returned the following error, which was much more meaningful and appropriate:

%RMS-E-FNF, file not found

RESPONSE

This problem was fixed in VAX/VMS Version 4.1.

OPERATING SYSTEM: VAX/VMS V4.0
PRODUCT: VAX/VMS
COMPONENT: RMS

Seq. 40.45.5

Access control string parsed incorrectly

PROBLEM
STATEMENT

In addition to the user name and password, if an account name is specified in the access control string of a DECnet node specification, there are cases when the password is incorrectly conveyed to the remote node. For example, this occurs when attempting to copy a file from a remote node to the local system.

RESPONSE

Several utilities, including COPY, use the RMS option open-by-file-id for accessing their input files. This function is simulated for DECnet file access, and the logic within RMS which performs this does not properly detect a masked password in the access control string. Thus, the masked password is not replaced by the real one.

This problem is fixed in VAX/VMS Version 4.2.



*

*



*

*



VERSION 4 ENHANCEMENTS

VERSION 4 ENHANCEMENTS

We are introducing a new section in the Dispatch entitled "Version 4 Enhancements." During the development of VAX/VMS Version 4, VMS added many new features, enhanced numerous components, and changed and modified existing code. In future issues of the Dispatch, VMS developers will be writing articles clarifying these changes that, based on problem reports we have received, appear to be sources of confusion.



Enhancements in Version 4.0 DCL

The following list provides an abstract of major VAX/VMS Version 3.n DCL problems and suggested enhancements that have been addressed in VAX/VMS Version 4.0.

PROBLEMS

PROBLEM

The SPAWN and ATTACH commands function improperly when executed from a command procedure.

RESPONSE

The use of SPAWN and ATTACH from within a command procedure is now fully supported.

* * *

PROBLEM

Executing a command procedure having STREAM_LF format causes the process to abort.

RESPONSE

Command procedures written in STREAM_LF format now function properly.

* * *

PROBLEM

The LIB\$SPAWN RTL routine translates input/output file specifications in both the parent process and subprocess if the file specification contains a concealed process logical name. This requires the presence of the process logical name table in the subprocess.

RESPONSE

The VAX/VMS Version 4.0 behavior parses the input/output file specifications completely prior to propagating them to the subprocess.

* * *

PROBLEM

There is currently no way to propagate the current state of the parent's command tables to a subprocess in a SPAWN operation. Therefore, any new commands which are added and are not present in the default command tables, are not inherited by the subprocess.

RESPONSE

The /TABLES qualifier on the SPAWN command allows an installed private command table to be used by a subprocess.

* * *

PROBLEM

DCL does not trap symbols that are greater than 512 bytes. The symbol value given by the SHOW SYMBOL command is truncated without any notification.

RESPONSE

The SHOW SYMBOL command now displays an optional informational message indicating symbol value truncation.

SUGGESTIONS

SUGGESTION

The CLI\$DCL_PARSE utility routine should be enhanced to support the use of continuation lines and prompt for missing parameters.

RESPONSE

CLI\$DCL_PARSE now includes both of these features.

* * *

SUGGESTION

A DCL command should exist that shows the version limits, set by SET DIRECTORY/VERSION_LIMIT or SET FILE/VERSION_LIMIT commands, for a given file or group of files.

RESPONSE

The DIRECTORY/FULL command now shows version limits currently in effect. This is displayed in the file attributes section.

* * *

SUGGESTION

The F\$LOGICAL lexical function should allow the logical name table, used in the translation, to be returned and/or specified.

RESPONSE

A new lexical function, F\$TRNLNM, is present in VAX/VMS Version 4.0 which replaces F\$LOGICAL. F\$LOGICAL is now obsolete, although it still exists for compatibility reasons. One of the many new features of F\$TRNLNM is the ability to specify the logical name table to be searched.

SUGGESTION

The ability should exist to specify a timeout period for the INQUIRE command and perform some default action whenever a timeout occurs.

RESPONSE

The READ/TIME_OUT command provides this ability.

The DCL command READ/PROMPT="string"/TIME_OUT=n performs essentially the same function as the INQUIRE command. If the READ command terminates with a timeout, it sets the \$STATUS value to %X181B0 (RMS-W-TMO). The \$STATUS symbol can then be used to branch conditionally to an error routine.

* * *

SUGGESTION

It should be possible to redirect all of DCL's output to a file.

RESPONSE

This is possible by creating a supervisor-mode (default mode for the ASSIGN and DEFINE commands) logical name in the process table which equates SYS\$OUTPUT to a file name. This automatically creates and opens the file. Deassign SYS\$OUTPUT to close the file and redirect the output back to the default device.

* * *

SUGGESTION

It should be possible to retrieve the name of the command procedure currently executing.

RESPONSE

This ability exists in the form of a new lexical function, F\$ENVIRONMENT. Specify F\$ENVIRONMENT("PROCEDURE") to return the name of the currently executing command procedure.

ARTICLES OF GENERAL INTEREST



OPERATING SYSTEM: VAX/VMS V4.1
PRODUCT: VAX/VMS
COMPONENT: DUDRIVER

Seq. 95.5.5

System disk mount verification timeout

PROBLEM STATEMENT

A cluster hang followed an HSC failure. Both systems hung; sometime later, one system crashed and the other continued to hang.

RESPONSE

The sequence of events that resulted in this behavior appears to be as follows.

The HSC experienced a problem which eventually resulted in an HSC crash and reboot. Both CPUs went into a hang condition since they were both in mount verification, waiting for the system disk (which was on the HSC). One CPU eventually timed out mount verification on the system disk, and any further I/O to the system disk failed with a page read error because the volume was invalid. This is the reason the system crashed. The other CPU continued to hang because it had not yet timed out the mount verification or simply had no I/O outstanding on that disk at the time. Eventually, it might have experienced a crash like the first CPU.

A mount verification timeout usually results in the volume being invalid until it can be dismounted and remounted. Since it is not possible or meaningful to dismount the system disk, mount verification timeout on the system disk is fatal.

We believe that the error which caused the HSC to crash and reboot is directly related to either hardware or microcode within the HSC. If this problem continues, field service should examine all the HSC console logs to determine the problem.

If mount verification timeout on the system disk continues to be a problem, consider raising the value of the SYSGEN parameter MVTIMEOUT. This increased value should equal the time which the user is willing to wait for a disk before giving up and attempting to continue without it.

We expect to modify mount verification in a future VAX/VMS update so that the system disk never experiences mount verification timeouts.

OPERATING SYSTEM: VAX/VMS
PRODUCT: VAX/VMS
COMPONENT: RMS

Seq. 95.5.6

DIRECTORY and search list confusion

PROBLEM STATEMENT

Using a common system disk, if the following command sequence is performed:

```
$ SET DEFAULT SYS$MANAGER  
$ DIRECTORY SYS$COMMON:SYSTARTUP.COM
```

two copies of the file are displayed even though there is only one file present. However, the command sequence:

```
$ SET DEFAULT SYS$MANAGER  
$ DIRECTORY SYS$SPECIFIC:[SYSMGR]SYSTARTUP.COM
```

correctly displays one copy of the file.

RESPONSE

This behavior results from the way RMS interprets search lists, and the effects that the search lists can have when used with SET DEFAULT. To help explain this behavior, following is a description of some of the underlying rules that RMS uses when parsing file names.

- o RMS considers search-listed logical names a directive to "look" in n places, where n is the number of translations available for the logical name. It is not a wildcard. As a result, no effort is made to determine if any specific translation is unique within the search list. RMS only knows that it should attempt to use each translation in turn, until the requester is satisfied.

- o SET DEFAULT sets up two file name fields, not one, and they are interpreted at different times. Specifically, it sets up SYS\$DISK with the device portion of the SET DEFAULT string and then sets up the default directory string with the directory portion. SYS\$DISK is used first when parsing a file name and, with the advent of both concealed logical names and search lists, it must be evaluated whenever either the device or directory is missing from the filespec.

RMS is given a filespec which is missing a directory. Because of the above rules, it first attempts to use SYS\$DISK. SYS\$DISK contains a search list of two items, so RMS evaluates this logical name twice before giving up. Note that, even though SYS\$DISK will never be used, RMS must still look through the search list in the event that later translations will be used. Since search lists are not wildcards, the fact that the results are not unique is irrelevant.

We intend to document this area more clearly in a future update of VAX/VMS.

"Does anybody really know what time it is? Does anybody really care?"

There are several problems associated with how the time and date are maintained in VAX/VMS. We must first present some background.

VAX/VMS makes use of several clocks, some in hardware and some in software, to keep track of the date and time. Because none of the available clocks solves all the problems of time keeping, they must be used in concert and be maintained in synch by the operating system. Under some circumstances, they might get out of synch, causing obscure and sometimes incomprehensible problems with the system date and time.

The master clock is maintained as a software construct by VAX/VMS. It is a cell in the EXEC that contains the current date and time in the VMS quadword time format. This value represents the time elapsed since 17-Nov-1858 in tenths of microseconds.

Most VAX CPUs provide two hardware clocks from which the VMS master clock is derived. The interval timer is used to provide an interrupt every 10 milliseconds. At each interrupt, the quadword master clock is incremented by the value 100,000, and time-dependent scheduling activities are initiated.

A time-of-year (TOY) clock is built into the console subsystem of most VAX CPUs. This clock is a 32-bit counter that is incremented every 10 milliseconds, whether the CPU is running or not, and, if battery backup is available, whether power is on or not. Every time VMS is booted, the software master clock is set from the TOY clock. This is where the trouble starts. The 32-bit, 100Hz counter has a capacity of 497 days and, therefore, cannot be used by itself to represent time over an indefinite period.

VMS uses the TOY clock to maintain the date and time relative to the current year and stores the current year on the system disk in the system image file SYS.EXE. This value is updated whenever the system time is recalibrated (when the system is booted or when a SET TIME command with no explicit time is entered). What is saved in the system image is the quadword master clock value and the TOY clock value that corresponds to it in the current year. To recalibrate the time, the TOY clock is read and a delta is computed from the saved TOY clock value. This delta is converted into quadword time units and is added to the saved quadword time,

Seq. 95.5.7

to yield the new current master clock value. If the TOY clock is found to have more than a year of time accumulated on it, one year's worth of time is subtracted and the new value is set in the TOY clock. Finally, the new TOY clock and master clock values are saved in the system image.

VMS adds a bias of $2^{*}28$ (31 days) to the time since January 1 to compute the value maintained in the TOY clock. Thus, should the TOY clock be reset or overflow, the value read will likely be less than the bias and will be rejected as an invalid clock value. Also, if the value read from the TOY clock is a day or more earlier than the saved value, it is rejected as invalid. Because of the bias, the TOY clock overflows 100 or 101 days after the first of the new year, depending on whether or not the previous year was a leap year. Thus, provided the system is rebooted or a SET TIME command is performed some time between January 1 and April 11 of each year, the TOY clock and system time will be correctly maintained indefinitely.

Problems arise when more than one copy of VMS is run on the same machine (for example, one's normal system and stand-alone BACKUP) and when new copies of the VMS EXEC are booted for the first time. For example, if two different copies of VMS are used at different times on the same machine, only one system will be presented with the opportunity to reset the TOY clock when it is first booted after January 1. The other system, when subsequently booted, will find that the TOY clock has a much smaller value than its saved value (from the last boot) and will reject the time as invalid, causing it to prompt for a new date and time.

When a new VMS system is distributed, it has assembled into it a quadword time and saved TOY clock value that represent January 1 of the current year. For example, VAX/VMS Version 4.0 was completed in October 1984; therefore, its internal time as distributed is based in 1984. Should a new copy of a system image be booted in a subsequent year, the TOY clock will be evaluated against the base date assembled into the system, and it will come up with the date set to approximately the current day in the year 1984. This will happen, for example, with the stand-alone BACKUP kit distributed with VMS magnetic tape kits. The problem with stand-alone BACKUP is particularly bothersome because its system time is never updated when it is booted. The disk it is being booted from is either write-locked or SYS.EXE is no longer present because the first floppy or TU58 has been removed.

CUMULATIVE INDEX

VAX/VMS SYSTEMS DISPATCH
CUMULATIVE INDEX FOR VAX/VMS V4.n
SEPTEMBER 1985

Following is a cumulative listing of articles for VAX/VMS V4.n and layered products.

The following list is designed so that in future issues it can be expanded. Consequently, there are several numbers "reserved" for that purpose. Also, within each category the numbering scheme allows for expanding the primary category to include related subsets. For example, under 55.0, Utilities, 55.35 is used for the COPY utility, 55.60 is used for the DIFFERENCES utility, etc. Periodically, the components list is reviewed to insure that it accommodates the current software needs.

R = indicates a republished article

<u>Component/ Product</u>	<u>Sequence Number</u>	<u>Title of Article</u>	<u>Operating System</u>	<u>Mon/Yr</u>
	1.0	<u>NEWS BULLETIN SECTION</u>		
NEWS BULLETIN	1.1.1	IMPORTANT VAX/VMS VERSION 4.2 INFORMATION	V4.2	Sep 85
	5.0	<u>EXECUTIVE & SYSTEM SERVICES SECTION</u>		
SYS	5.20.1	F\$GETDVI INFORMATION INVALID IF DISK NOT MOUNTED	V4.0	Jul 85
	5.20.2	EXCESSIVE MODIFIED PAGE LIST WRITING	V4.0	Jul 85
	5.20.3	GETJPI PROC INDEX VALUE	V4.0	Jul 85
	5.20.4	SHUTDOWN WITH REBOOT CHECK CAN FAIL	V4.0	Jul 85
	5.20.5	TODR DEFINITION REMOVED IN VAX/VMS VERSION 4.0	V4.0	Jul 85
	5.20.6	SCREEN MANAGEMENT SYMBOLS DEFINED INCORRECTLY	V4.0	Jul 85
	5.20.7	TEMPORARY MAILBOX LOGICAL NAMES	V4.0	Jul 85
	5.20.8	LACK OF DISK QUOTA CAUSES ERRFMT TO FAIL	V4.0	Sep 85
	5.20.9	GETJPI ("","TERMINAL") TRUNCATES NAMES	V4.0	Sep 85
	10.0	<u>SYSTEM MANAGEMENT, OPERATIONS & SECURITY SECTION</u>		
ACCOUNTING	10.5.1	PROBLEMS WITH ACCOUNTING SELECTION BY UIC	V4.0	Jul 85
	10.5.2	USER RECORD DISPLAYS SCROLL OFF SCREEN	V4.0	Jul 85
STARTUP	10.15.1	TERMINAL LOGICAL NAMES IN UVSTARTUP.COM	V4.0	Sep 85
	11.0	<u>OPERATIONS SECTION</u>		
LOGINOUT	11.15.1	INCORRECT VALIDATION OF MAXJOBS	V4.0	Sep 85
	11.15.2	DEFCLI PROHIBITS CLI TABLE CHANGE IN SPAWN	V4.0	Sep 85
	11.15.3	NETWORK JOBS NOT COUNTED AGAINST MAXJOBS	V4.1	Sep 85
SYSBOOT	11.30.1	TOPSYS SYSTEM ROOT IS INCORRECT	V4.0	Sep 85
SYSGEN	11.35.1	DISCREPANCY IN SCSNODE NAME LENGTH	V4.0	Jul 85
SYSINIT	11.40.1	QUOTA CACHING DISABLED ON THE SYSTEM DISK	V4.0	Jul 85
	11.40.2	SYSUAF.DAT REDEFINED FOR BYPASS AT LOGIN	V4.0	Sep 85
	12.0	<u>SOFTWARE INSTALLATION SECTION</u>		
UPGRADE	12.10.1	CVTUAF DOES NOT COPY USER DATA AREA	V4.0	Jul 85
	12.10.2	VMSINSTAL FAILS DURING VERSION 4.0 UPGRADE ON TU81	V4.0	Jul 85
VMSINSTAL	12.15.1	VMIBCKERR.TMP INADVERTENTLY PLACED IN SAVE SET	V4.0	Jul 85
	12.15.2	VMSINSTAL GET OPTION FAILS ON VERSION 4 UPDATE	V4.0	Sep 85

<u>Component/ Product</u>	<u>Sequence Number</u>	<u>Title of Article</u>	<u>Operating System</u>	<u>Mon/Yr</u>
	15.0	<u>BATCH, PRINT, JOB CONTROLLER SECTION</u>		
JOBCTL	15.15.1	SNDSMB WITH FILESIZ OPTION FAILS	V4.0	Jul 85
PRINT	15.25.1	SYMBIONT ISSUES BLANK PAGES WITH /SETUP	V4.0	Jul 85
	15.25.2	SUGGESTION FOR DEFAULT FORM FOR EACH QUEUE	V4.0	Jul 85
PRINT SYMBIONT	15.30.1	HOW TO PRINT HEADERS IN 80-COLUMN FORMAT	V4.0	Jul 85
	15.30.2	UNEXPECTED SYMBIONT PROCESS TERMINATION	V4.1	Jul 85
	15.30.3	CANNOT BYPASS ALL FORMATTING IN PRINT SYMBIONT	V4.0	Sep 85
	15.30.4	PRINT SYMBIONT ALLOCATES OUTPUT DEVICE	V4.0	Sep 85
	15.30.5	MULTIPLE PAGE HEADERS GENERATED BY PLOT	V4.1	Sep 85
	15.30.6	LOSS OF PRINT JOB WHEN CARRIER IS DROPPED	V4.1	Sep 85
	15.30.7	FILE LEFT OPEN BY PRINT SYMBIONT	V4.1	Sep 85
	15.30.8	IMPLICIT SPOOLING RESTRICTS USER	V4.0	Sep 85
	15.30.9	PRINT SYMBIONT PERFORMS TAB EXPANSION	V4.0	Sep 85
	15.30.10	PRINT SYMBIONT PROCESS TERMINATION	V4.1	Sep 85
	15.30.11	PRINT SYMBIONT ENTERS COMPUTE LOOP	V4.1	Sep 85
	15.30.12	MISCELLANEOUS PROBLEMS IN PRINT SYMBIONT	V4.1	Sep 85
	15.30.13	SERIAL PRINTERS ON DMF DISCONNECT	V4.0	Sep 85
	20.0	<u>DCL SECTION</u>		
DCL	20.5.1	CAPTIVE ACCOUNT CAUSES LOGINOUT ACCESS VIOLATION	V4.0	Sep 85
	20.5.2	CANNOT CHANGE/EXAMINE LOGICAL NAME TABLE PROT	V4.0	Sep 85
	25.0	<u>DECnet SECTION</u>		
DECnet	25.5.1	NETWORK JOBS USE DEFAULT DCLTABLES	V4.0	Jul 85
	25.5.2	SPURIOUS NODE UNREACHABLE ERRORS	V4.0	Jul 85
	25.5.3	STARTNET.COM INCORRECTLY PARSES NODE ADDRESS	V4.0	Jul 85
	25.5.4	STARTNET.COM FAILS TO CHECK FOR ALTPRI PRIVILEGE	V4.0	Jul 85
	25.5.5	STREAM LF FILE TRANSFER HANGS TO NON-VMS PARTNERS	V4.0	Sep 85
	25.5.6	DECnet GIVES INCORRECT ERROR ON INVALID USER NAME	V4.1	Sep 85
	31.0	<u>DISK & TAPE DRIVERS SECTION</u>		
DDDRIVER	31.10.1	TU58 TIMES OUT WHEN /DATA_CHECK=WRITE IS USED	V4.0	Sep 85
	32.0	<u>NET DRIVERS SECTION</u>		
XDDRIVER	32.25.1	DEVICE FULL ERROR WHEN INITIALIZING DMP-11	V4.0	Jul 85
YQDRIVER	32.45.1	YQDRIVER CORRUPTS NONPAGED POOL	V4.0	Jul 85
	33.0	<u>TERMINAL DRIVERS SECTION</u>		
TTDRIVER	33.20.1	VT200 NOT DEFINED IN \$DCDEF	V4.0	Jul 85
	33.20.2	DMA NOT SET ON DMF-32 LINES	V4.0	Jul 85
	34.0	<u>OTHER DRIVERS SECTION</u>		
LPDRIVER	34.20.1	SYSTEM-F-EXQUOTA ERROR ON PRINTOUT	V4.0	Jul 85
	35.0	<u>EDITORS SECTION</u>		
EDIT/ACL	35.5.1	EDIT/ACL DELETES ACE GRANTING ACCESS	V4.0	Sep 85
	35.5.2	PROBLEM IN REFRESH LOGIC CAUSES ACCESS VIOLATION	V4.0	Sep 85
	35.5.3	MISSING STATUS RETURN	V4.0	Sep 85

<u>Component/ Product</u>	<u>Sequence Number</u>	<u>Title of Article</u>	<u>Operating System</u>	<u>Mon/Yr</u>
	40.0	<u>FILE SYSTEMS AND RMS SECTION</u>		
CONVERT	40.5.1	CONVERT/RECLAIM MAY ACCESS VIOLATE	V4.0	Sep 85 R
	40.5.2	CONVERT CAN INCORRECTLY REPORT DUP AND SEQ ERRORS	V4.0	Sep 85 R
	40.5.3	CONVERT INCORRECTLY RETURNS RTL ERROR	V4.0	Sep 85
RMS	40.45.1	READ FROM SYS\$OUTPUT FAILS	V4.0	Sep 85 R
	40.45.2	COPY/OVERLAY FAILS IF DESTINATION WRITE-PROTECTED	V4.0	Sep 85 R
	40.45.3	CONFUSION ON \$CREATE USING SEARCH LISTS	V4.0	Sep 85 R
	40.45.4	RENAME RETURNS INCORRECT ERROR MESSAGE	V4.0	Sep 85 R
	40.45.5	ACCESS CONTROL STRING PARSED INCORRECTLY	V4.0	Sep 85 R
	40.45.6	FILE CORRUPTION WITH GLOBAL BUFFERS	V4.0	Sep 85
	40.45.7	SYS\$RMSRUNDN RETURNS INCORRECT STATUS	V4.0	Sep 85
	40.45.8	SEARCH LIST QUESTIONS	V4.0	Sep 85
	40.45.9	REMOTE COMMAND PROCEDURES FAIL	V4.0	Sep 85
	40.45.10	VERSION 4 COPY WILL NOT COPY VERSION 3 ISAM FILES	V4.1	Sep 85
	40.45.11	RMS FILE PARSE PROBLEM WITH LEVEL 8 DIRECTORIES	V4.0	Sep 85
	45.0	<u>RTL SECTION</u>		
RTL	45.1.1	VAX BASIC PROGRAMS RETURN AN INCORRECT ERL FOR ERRORS 50 AND 52	V4.0	Jul 85
	55.0	<u>UTILITIES SECTION</u>		
ANALYZE	55.5.1	ANALYZE/IMAGE REPORTS INCORRECT LINK DATE AND TIME	V4.0	Jul 85
AUTHORIZE	55.10.1	AUTHORIZE HAS TROUBLE PARSING /<ACCESS> QUALIFIERS	V4.0	Jul 85
	55.10.2	REVOKE/IDENTIFIER DOES NOT REMOVE UICS	V4.0	Jul 85
	55.10.3	CLARIFICATION OF ADD/NETWORK	V4.0	Sep 85
	55.10.4	AUTHORIZE AND DISKQUOTA DO NOT RETURN STATUS	V4.0	Sep 85
	55.10.5	PROBLEM WITH SHOW/ID FOLLOWED BY MOD/ID	V4.0	Sep 85
BACKUP	55.20.1	PROBLEM BOOTING STANDALONE BACKUP	V4.0	Jul 85
DEBUG	55.50.1	SET MODULE COMMAND TAKES TOO LONG	V4.0	Sep 85
	55.50.2	COMMA LISTS ON DEPOSIT NOT ALLOWED	V4.1	Sep 85
DIRECTORY	55.65.1	DIRECTORY OUTPUT MISSING TOTAL LINE	V4.0	Jul 85
	55.65.2	DIRECTORY MAY DISPLAY NONEXISTENT FILES	V4.0	Jul 85
INITIALIZE	56.5.1	INITIALIZE/INDEX:BLOCK=N NOT RECOGNIZED	V4.0	Jul 85
INSTALL	56.10.1	INABILITY TO INSTALL EXECUTABLE IMAGES	V4.0	Jul 85
LIBRARIAN	56.15.1	PROBLEM DECOMPRESSING A LIBRARY	V4.0	Jul 85
LINKER	56.20.1	LINKER OPEN FILE LIMIT PROBLEM	V4.0	Jul 85
	56.20.2	LINKER REJECTS VALID FILE NAMES IN OPTIONS FILES	V4.0	Jul 85
	56.20.3	VERSION 4.0 IMAGES LARGER THAN VERSION 3.0 IMAGES	V4.0	Sep 85
MAIL	56.30.1	MAIL CANNOT RUN ON A GIGI TERMINAL	V4.0	Sep 85
MONITOR	56.40.1	FOREIGN TERMINAL SUPPORT DOES NOT WORK	V4.0	Sep 85
	56.40.2	MONITOR'S VIRTUAL MEMORY USAGE GROWS CONTINUOUSLY	V4.0	Sep 85
PURGE	56.52.1	PURGE CAN INCORRECTLY DELETE FILES	V4.0	Sep 85
SHOW	56.75.1	RANDOM BROADCAST CLASSES DISABLED	V4.0	Jul 85
SET	56.80.1	SET PASSWORD SIGNALS ERRORS TWICE	V4.0	Jul 85
	56.80.2	VOLUME RETENTION DATES OVERRIDE SET FILE DATES	V4.0	Sep 85
	56.80.3	SET PASSWORD ALWAYS RETURNS SUCCESS STATUS	V4.1	Sep 85

<u>Component/ Product</u>	<u>Sequence Number</u>	<u>Title of Article</u>	<u>Operating System</u>	<u>Mon/Yr</u>
SHOW CLUSTER	56.85.1	CNX_STATE DOCUMENTATION ERROR	V4.1	Sep 85
SHUTDOWN	56.90.1	SHUTDOWN\$INFORM_NODES USAGE DESCRIBED	V4.0	Sep 85
	56.90.2	TIME-OF-YEAR CLOCK CAUSES SHUTDOWN ERROR	V4.0	Sep 85
SPAWN	57.10.1	CANNOT SPECIFY SPOOLED DEVICE WITH SPAWN	V4.0	Sep 85
	57.10.2	LIB\$SPAWN FAILS WITH MBFULL	V4.0	Sep 85
	62.0	<u>VERSION 4 ENHANCEMENTS SECTION</u>		
ENHANCEMENTS	62.5.1	ENHANCEMENTS IN VERSION 4.0 DCL	V4.0	Sep 85
	65.0	<u>DOCUMENTATION SECTION</u>		
DOCUMENTATION	65.5.1	SYS\$TRNLNM EXAMPLE IS INCORRECT	V4.0	Jul 85
	65.5.2	SNDOPR SYMBOLIC CODE INCORRECT	V4.0	Jul 85
	65.5.3	UNDOCUMENTED ERROR MESSAGE FOR MOUNT	V4.0	Jul 85
	65.5.4	SYS\$GETJPI DOCUMENTATION ERRORS	V4.1	Sep 85
	65.5.5	SYS\$GETJPI DOCUMENTATION ERROR	V4.0	Sep 85
	65.5.6	CHAN ARGUMENT INCORRECT FOR \$GETDVI	V4.0	Sep 85
	85.0	<u>LANGUAGES SECTION</u>		
COBOL, IVP	85.25.1	WARNING MESSAGE CAUSES IVP TO FAIL	V4.0	Jul 85
PASCAL, STARLET	85.50.1	ERROR IN XAB\$ DEFINITIONS	V4.0	Jul 85
	95.0	<u>ARTICLES OF GENERAL INTEREST</u>		
OPCOM	95.5.1	BATCH/REMOTE ENABLE OF OPERATOR TERMINALS	V4.0	Jul 85
	95.5.2	ERRANT FORMATTING BEHAVIOR IN VAX/VMS PRINT SYMBIONT	V4.0	Jul 85
SYS	95.5.3	DELETION OF GLOBAL SECTIONS	V4.0	Jul 85
MICROFICHE	95.5.4	INCORRECT ENTRIES IN VERSION 4.1 MICROFICHE	V4.1	Jul 85
DUDRIVER	95.5.5	SYSTEM DISK MOUNT VERIFICATION TIMEOUT	V4.1	Sep 85
RMS	95.5.6	DIRECTORY AND SEARCH LIST CONFUSION	V4.0	Sep 85
DATE/TIME CLOCK	95.5.7	"DOES ANYBODY REALLY KNOW WHAT TIME IT IS? DOES ANYBODY REALLY CARE?"	V4.n	Sep 85

COMPONENTS LIST

DISPATCH INDEX

- 1.1 News Bulletins
- 5.0 Executive and System Services
 - 5.5 IMAGE ACTIVATOR
 - 5.10 LOGICAL NAMES
 - 5.15 MEMORY MANAGEMENT
 - 5.20 SYS
- 10.0 System Management, Operations & Security
 - 10.0.0 System Management
 - 10.5 ACCOUNTING
 - 10.10 SDA
 - 10.15 STARTUP
- 11.0 Operations
 - 11.5 ERROR LOGGING
 - 11.10 EVENT LOGGING
 - 11.15 LOGINOUT
 - 11.20 OPCCRASH
 - 11.25 OPCOM
 - 11.30 SYSBOOT
 - 11.35 SYSGEN
 - 11.40 SYSINIT
 - 11.45 VMB
 - 11.50 WRITEBOOT

12.0	Software Installation
12.10	UPGRADE
12.15	VMSINSTAL
13.0	Security
15.0	BATCH, PRINT, JOB CONTROLLER
15.5	BATCH
15.10	INPUT SYMBIONT
15.15	JOB CONTROLLER
15.20	LOCK MANAGER
15.25	PRINT
15.30	PRINT SYMBIONT
15.35	QUEUE MANAGER
20.0	DCL
25.0	DECnet
25.5	DECnet (generic)
25.10	DDCMP
25.15	DTS/DTR
25.20	EVL
25.25	FAL
25.30	HLD
25.35	MIRROR
25.40	MOM
25.45	NCP
25.50	NETACP

25.55 NML
25.60 REMACP
25.65 RTPAD (SET HOST)

30.0 Drivers

30.5 Console Drivers

31.0 Disk & Tape Drivers

31.5 DBDRIVER
31.10 DDDRIVER
31.15 DLDRIVER
31.20 DMDRIVER
31.25 DQDRIVER
31.30 DRDRIVER
31.35 DUDRIVER
31.40 DYDRIVER
31.45 MTDRIVER
31.50 TFDRIVER
31.55 TMDRIVER
31.60 TSDRIVER
31.65 TUDRIVER

32.0 NET Drivers

32.5 CNDRIVER
32.10 NDDRIVER
32.15 NETDRIVER
32.20 NODRIVER
32.25 XDDRIVER
32.30 XEDRIVER

32.35	XGDRIVER
32.40	XMDRIVER
32.45	XQDRIVER
32.50	XWDRIVER

33.0 Terminal Drivers

33.5	CTDRIVER
33.10	DZDRIVER
33.15	RTTDRIVER
33.20	TTDRIVER
33.25	YCDRIVER
33.30	YFDRIVER

34.0 Other

34.5	CRDRIVER
34.10	DXDRIVER
34.15	LADRIVER
34.20	LPDRIVER
34.25	LTDRIVER
34.30	MBDRIVER
34.35	MBXDRIVER
34.40	PADRIVER
34.45	PUDRIVER
34.50	XADRIVER
34.55	XGDRIVER
34.60	XIDRIVER
34.65	XJDRIVER
34.70	XKDRIVER
34.75	XMDRIVER

35.0	EDITORS
35.5	EDIT/ACL (ACLEDT)
35.10	EDIT/FDL
35.15	EDIT/SUM
35.20	EDT
35.25	TECO
35.30	TPU
40.0	File systems and RMS
40.5	CONVERT
40.10	F11AACP
40.15	F11BXQP
40.20	FDL
40.30	MOUNT
40.40	MTAACP
40.45	RMS
45.0	RTL
50.0	UETP
55.0	Utilities
55.5	ANALYZE/xxx
55.10	AUTHORIZE
55.15	AUTOGEN
55.20	BACKUP
55.25	CDU
55.35	COPY
55.40	CREATE

55.45	CROSS REFERENCE
55.50	DEBUG
55.55	DELETE
55.60	DIFFERENCES
55.65	DIRECTORY
55.70	DISKQUOTA
55.75	DISMOUNT
55.80	DR32
55.85	DUMP
55.90	EXCHANGE
55.95	HELP
56.5	INITIALIZE
56.10	INSTALL
56.15	LIBRARIAN
56.20	LINKER
56.25	MACRO
56.30	MAIL
56.35	MESSAGE
56.40	MONITOR
56.45	PATCH
56.50	PHONE
56.52	PURGE
56.55	RECALL
56.60	RENAME
56.65	REPLY
56.70	REQUEST
56.75	SEARCH

	56.80	SET/xxx
	56.85	SHOW/xxx
	56.90	SHUTDOWN
	57.5	SORT
	57.10	SPAWN
	57.15	SUBMIT
	57.20	TYPE
60.0	VAXcluster-related articles	
62.0	Version 4 Enhancements	
65.0	Documentation	
70.0	Layered Products	
	70.5	Applications & Utilities
	70.10	VAX ADE
	70.15	VAX DEC/CMS
	70.20	VAX DECmail
	70.25	VAX DEC/MMS
	70.30	VAX FMS
	70.35	RSX-11S (EDI, FLX)
	70.40	VAX DECalc
	70.45	VAX TDMS
75.0	Communications	
	75.5	VAX 2780/3780 Protocol Emulator
	75.10	VAX 3271 Protocol Emulator
	75.15	ETHERNET TERMINAL SERVER
	75.20	SNA

75.25	LAT-11
75.30	MESSAGE ROUTER
75.35	MUX200/VAX
75.40	VAX BTS
80.0	Data Management
80.5	VAX CDD
80.10	VAX DATATRIEVE
80.15	VAX DBMS
80.20	VAX Rdb/VMS
85.0	Languages
85.5	VAX Ada
85.10	VAX BASIC
85.15	VAX BLISS-32
85.20	VAX C
85.25	VAX COBOL
85.30	VAX CORAL 66
85.35	VAX DIBOL
85.40	VAX FORTRAN
85.45	VAX MACRO
85.50	VAX PASCAL
85.55	VAX PL/1
90.0	Workstations
95.0	Articles of General Interest
100.0	Hardware Related Information

SOFTWARE PROBLEMS OR ENHANCEMENTS

Questions, problems, and enhancements to DIGITAL software should be reported on a Software Performance Report (SPR) form and mailed to the SPR Center at one of the following Digital Offices: (SPR forms are available from the SPR Center).

Areas Covered

United States;
remainder of Far East,
Middle East, Africa
Latin America

Canada

United Kingdom, Bahrain,
Egypt, Iraq, Jordan, Kuwait,
Lebanon, Libya, Qatar,
Oman, Saudi Arabia, Syria,
United Arab Emirates, Yemen,
Arab Republic

Australia, New Zealand

Brazil

Caribbean

France

Italy

Japan

Belgium, Holland,
Luxemburg

SPR Center

Corporate Administrative Services Group
P.O. Box F
Maynard, MA 01754

Digital Equipment of Canada, Ltd.
P.O. Box 13000
Kanata, Ontario
Canada, K2K 2A6

Digital Equipment Co. Ltd.
2 Cheapside
GB - Reading, Berkshire RG1 7AA
England

Digital Equipment Aust. Pty. Ltd.
P.O. Box 384
Chatswood, New South Wales 2067
Australia

Digital Equipment Comercio e
Industria Ltda.
Avenida Augusto Severo, 156-A
20021 Rio de Janeiro, RJ
Brazil

Digital Equipment Latin America
P.O. Box 11038
Fernandez Juncos Station
Santurce 00910
Puerto Rico

Digital Equipment France
Cidex L225
18 Rue Saarinen
F-94528, Rungis
France

Digital Equipment S.p.A.
Viale Fulvio Testi, 11
Ang. Via Gorki 105
I-20092 Cinisello Balsamo
Milan
Italy

Digital Equipment Corp. Intl. Japan
Sunshine 60, P.O. Box 1135
1-1 Higashi Ikebukuro 3-Chome.
Toshima-Ku, Tokyo, 170
Japan

Digital Equipment B.V.
Kaap Hoorndreef 38
NL-3563 AV Utrecht
Holland

Sweden	Digital Equipment AB P.O. Box 1250 S-17124 Solna 1 Sweden
Denmark	Digital Equipment Corp. AS Kristineberg 3 DK-2100 Copenhagen 0 Denmark
Finland	Digital Equipment Corp. Oy PL 16 SF-02201, Espoo 20 Finland
Norway	Digital Equipment Corp. A/S Pottemakerveien 8 N-Oslo 5 Norway
Austria, East Germany, West Germany, Poland, Hungary, Rumania, Czechoslovakia, Russia, Bulgaria	Digital Equipment Corp. GmbH Rheinstrasse 28 D - 8000 Munich 40 West Germany
Israel	Decsys, Computers Ltd. 4, Yirmiyahu Str. IL-63505 Tel Aviv Israel
Greece, Portugal, Spain, Switzerland, Yugoslavia, (Morocco, Algeria, Tunisia, Cyprus, Turkey, Malta)	Digital Equipment Corp. SA 9, Route des Jeunes Case Postale 191 CH-1211 Geneva 26 Switzerland
Mexico	Digital Equipment de Mexico, S.A. de C.V. Ave. Lopez Mateos 427, 1st. Floor Guadalajara Jalisco Mexico
China	Digital Computer Hong Kong Ltd. 1303-1309 Dominion Ctr. 43-59 Queen's Road East Wanchai Hong Kong

This data sheet explains what software licenses are and why customers must obtain a software license to run any item of DIGITAL proprietary software.

DIGITAL does not sell software; DIGITAL offers software under a license agreement. DIGITAL has a license agreement for source software and object software. Since DIGITAL software programs are made available primarily in object code, this data sheet focuses on the purchase of object programs.

Introduction to Software Licensing

When DIGITAL hardware is purchased, all rights of ownership (legally called "title") to the hardware pass to the customer. This is not the case with software. DIGITAL regards software as proprietary information. Since software is easily reproduced, it must be legally protected from improper copying. Therefore, DIGITAL uses a combination of trade secret and copyright legal protection for software. DIGITAL protects its investment by retaining title to its software at all times and requires anyone wishing to use it to obtain a license.

How DIGITAL Licenses Software

The license agreement for object programs is contained in DIGITAL's standard Terms and Conditions of Sale and Corporate Volume Purchase Agreements instead of as a separate agreement. Therefore, when software products are purchased under DIGITAL's Terms of Sale, the software license agreement is made at the same time.

Key Principles of the License Agreement

Object code is licensed for single use. This means obtaining a license for a product allows the associated software to be used on the "single" CPU on which it was first installed. Other key points are as follows:

- If the licensed CPU temporarily malfunctions, the software may be run on another machine while the CPU is down.
- Copies of the software may be made for backup purposes if appropriate proprietary and copyright notices are included.
- The software may be modified or merged with other software if appropriate proprietary and copyright notices are included.
- The software may be used by the customer's employees and its agents directly concerned with the internal use, but may not be made available to anyone else.

Modification to the Software Product

Any modification to licensed software does not exempt the product from DIGITAL license terms. Every line of code from a software product falls under the terms of the license. Only those modifications that are not part of the original software are the customer's property. It is important to note that warranty on the product is limited to the original software supplied by DIGITAL.

Transferability of Licensed Software Products

License Transfer - A license agreement does not automatically allow transfer of licensed software to another party or another CPU. If the customer intends to sell the licensed CPU and pass on the software with the sale or move the software onto another CPU, permission must be obtained from DIGITAL. A case-by-case License Transfer is required to relicense the software.

Software Sublicensing - DIGITAL customers with a purchase agreement authorizing sublicensing, such as OEMs, may transfer licensed object products to their customers without a License Transfer. A valid sublicense, executed by an OEM with its customer, gives the OEM's customer the same license rights and responsibilities as a license agreement made directly with DIGITAL.

Source Software

Sources are only available for selected products. A license agreement for source software must be separately executed for each facility/location which intends to purchase sources in machine-readable, listing, or microfiche form. Further information and availability of sources can be found in the applicable Software Product Description (SPD).

Software Warranty

Each licensed software product offered has an SPD describing the warranty commitment for the product. Software products under DIGITAL warranty must conform to the description provided for a 90-day period, which generally begins upon product installation or 30 days after delivery. All other products are provided AS IS, without warranty. The SPD clearly states under which warranty category the product falls.

Purchasing the License for the Software Product

A license must be obtained for each CPU on which the licensed software will be used (unless otherwise specified by DIGITAL).

A Single-use License for object code is generally ordered according to the type/classification of the CPU or system configuration intended to run the product. Further information and availability can be found in the applicable SPD.

Software Product

A license is a prerequisite to purchase the associated software. The Media and Documentation Option for a product is ordered according to media type. Further information and availability of media can be found in the applicable SPD.

Purchasing Software Product Revisions/Updated Versions

If a licensed customer is not covered by a product service agreement, updated versions can be purchased when they are made generally available. Updated versions are ordered according to media type. A customer can also choose to run updated versions on additional CPUs, but not purchase multiple media distributions. If this is the case, the Software Revision Right-to-Copy option must be purchased for each CPU which runs the updated version.

Software Product Services

A licensed customer can purchase annual product service agreements to receive updated versions on media when available. A customer may choose to copy updated versions onto additional CPUs during this service agreement period. In this case, the software Service Right-to-Copy must be purchased for each CPU which runs the updated version. Further information and availability can be found in the applicable SPD. Your local DIGITAL office can be contacted for additional assistance.

DIGITAL EQUIPMENT COMPUTER USERS SOCIETY

BENEFITS OF BELONGING

The Digital Equipment Computer Users Society (DECUS) is one of the largest and most respected users groups in the computer industry today. Membership in DECUS, which is free and voluntary, provides the individual user with information and services not found anywhere else.

DECUS provides an environment where users of Digital Equipment Corporation products can share information with other users and with DIGITAL. Members can find out the latest news on DIGITAL's hardware, software, and educational products. The feedback exchange with DIGITAL allows the users of DIGITAL's products to have a voice in the company's future.

Founded in 1961, DECUS now has three autonomous areas worldwide - DECUS U.S., DECUS Europe, made up of eight independent chapters, and DECUS GIA (General International Area), made up of four independent chapters. DECUS services and activities are shared between these chapters through mutual agreements.

All DECUS services promote the exchange of information in a noncommercial environment. Included in these services are:

Special Interest Groups (SIGs)

These groups, formed around an area of common interest, exist for a variety of hardware, operating systems, languages, applications, and marketing areas. Participation in these groups allows fellow users to exchange information and share technical expertise in the areas of most interest to the users.

Local Users Groups (LUGs) and National Users Groups (NUGs)

LUGs and NUGs are licensed groups of individuals who gather to share information with other users on a periodic basis. Not only do they have common professional interest, but they also have geographic and cultural ties. DIGITAL representatives attending these meetings often unveil new products and services and supply updates on existing policies and procedures.

Symposia

DECUS holds symposia each year in the different chapters, two per year in the U.S. These meetings provide a unique opportunity for users with a wide spectrum of experience to meet for up to five days of intensive technical exchange. Symposium activities include workshops, clinics, panels, tutorials, and formal paper presentations. DIGITAL participates in symposia by sending Product Group managers and developers to discuss strategies, products, problems, and solutions.

Publications

The flow of information among users, as well as between users and DIGITAL, is the primary goal of DECUS. Various publications generated by DECUS support this communication. They include chapter newsletters and *The Proceedings*, a technical volume published after each symposium. DECUS also publishes Special Interest Groups' newsletters that provide information pertaining to specific DIGITAL products.

Program Library

The DECUS Program Library is the main vehicle for the exchange of software among users of all DIGITAL systems. The Library contains over 1000 software programs written and voluntarily submitted by users. These programs include compilers, editors, utilities, numerical and statistical functions, as well as games and graphic routines. The Library publishes an annual software catalog that lists and describes all the DECUS programs available to all users for a minimal charge.

You are cordially invited to join over 60,000 other users of DIGITAL products around the world and begin to share your experiences, both successes and problems.

For more information, contact the appropriate DECUS chapter office listed here.

DECUS CHAPTER OFFICES — WORLDWIDE

DECUS U.S.

DECUS, U.S. Chapter
249 Northboro Road (BPO2)
Marlborough, Massachusetts 01752
U.S. Activities: (617) 480-3259 (3302)
Library: (617) 480-3521
Finance and Administration: (617) 480-3634

DECUS Europe

DECUS At Large (in Europe)
C.P. 510
CH-1213 PETIT-LANCY 1/GE
Switzerland

DECUS France
B.P. 136
F-91004 EVRY CEDEX

DECUS Holland
Kaap Hoorndreef 38
NL-3563 AV UTRECHT
The Netherlands

DECUS Muenchen
Freischuetzstrasse 91
D-8000 MUENCHEN 81
Federal Republic of Germany

DECUS Italia
Viale Fulvio Testi 11
I-20092 CINISELLO BALSAMO

DECUS Nordic
S-172 89 SUNDBYBERG
Sweden

DECUS U.K., Ireland and
Middle East
P.O. Box 53
READING, RG2 OTW
U.K.

DECUS Switzerland
Schaffhauserstrasse 144
8302 Kloten
Switzerland

DECUS GIA (General International Area)

DECUS Australia
Northern Tower, Chatswood Plaza
Railway Street
Chatswood, New South Wales 2067
Australia
Phone: (02) 412.5237

DECUS Canada
100 Herzberg Road
P.O. Box 13000
Kanata, Ontario K2K 2A6
Canada
Phone: (613) 592-5111, ext. 2115

DECUS Japan
Nihon Digital Equipment KK
Sunshine 60, P.O. Box 1135
1-1, Higashi Ikeburo 3-Chome
Toshima-ku, Tokyo 170
Japan
Phone: [81]-(3)-9897111

DECUS GIC
100 Nagog Park AKO1-1/B11
Acton, Massachusetts 01720
U.S.A.
Phone: (617) 264-6561



July 1984